Submit 3 Copies to Appropriate District Office	State of New Mexi Energy, Minerals and Natural Re		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs NM 88240 DISTRICT II 811 S. 1st Street, Artesia, NM 88210-28	OIL CONSERVATION P.O. Box 208 Santa Fe, New Mexico 8	8	WELL API NO. 30-015-28589 5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE X FEE 6. State Oil & Gas Lease No. E 10169
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Stinking Draw
1. Type of Well: OIL WELL X GAS WELL OTHER			
2. Name of Operator Marathon Oil Company			8. Well No. 4
3. Address of Operator P.O. Box 552, Midland,	TX 79702		9. Pool name or Wildcat Dagger Draw U. Penn Assoc S.
4. Well Location Unit Letter 0: 970 Feet From The South Line and 2076 Feet From The East Line			
Section 36	Township 20 1/2 South _{Rar}		NMPM Eddy County
GL:3653 KB:3668.5 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
·			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER: Add Perfs	X	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. MIRU PU. NU BOP. POOH with rods and tubing. Perforate 7760-7780 7794-7800 with 2 JSPF 23 gram tungsten lined charges. Using Pinpoint injection packer acidize 7800-7794, 7780-7760 with total of 3250 gallons acid. Set PPI @ 7660'. Swab back load. Install submersible pumping equipment. ND BOP. Nu tree. Put well on test.			
			·
			ON CONTRACTOR
I heraby partify that the information shows	is true and complete to the hest of my knowledge	a and halinf	