Form 3160-5	N.M. OII CON UNITED STATES 811 S. 1st Stre PEPARTMENT OF THE INTERIO	FORM APPROVED
	UREAU OF LAND MANAGEMENT	
D	OREAU OF LAND MANAGEMENT	February 08, 1996 5. Lease Designation and Serial No.
		-
SUNDRY NOTICES AND REPORTS ON WELLS		NCLC-069219
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir Use "APPLICATION FOR PERMIT" for such proposals		oir 6. If Indian, Allotee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well	Gas Weil Other	BIG EDDY UNIT
2. Name of Operator		8. Well Name and No.
Bass Enterprises Production	Company	N. INDIAN FLATS 26 FEDERAL #2
3. Address and Telephone No.		9. API Well No.
P. O. Box 2760		30-015-28702
Midland, Texas 79702-2760	(915) 683-2277	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., N		INDIAN FLATS (DELAWARE) 11. County or Parish, State
1650' FSL & 2310' FEL, UNI	I LETTER J, SECTION 26. T-21-S, R-28-E	EDDY COUNTY, NEW MEXICO
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	X Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Casing Repair Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
Bass Enterprises Production Co. proposes to plug and abandon the above referenced well. The proposed plugging procedure is as follows:		
· · ·	m the existing cast iron bridge plug (@ 3640') up to 2675'. Pre e-spot cement if top is found below 3525' (50' above top perf).	ssure cement and establish a 500 psi squeeze.
3) Spot a 20 sack (195') cement plug at the top of the Delaware formation (2767' to 2572').		
	base of the surface casing (380' to 185').	and the second
5) Spot a 50' (6 sack) surface plug.		
6) Cut off wellhead. Install dry hole marker. Rip and re-sead location, roads and pits.		
7) File final abandonment notice.		
	별시가 (인터스) 위험을 받는다. 전자 관금 국가 시작하는 프로그램	n an
	a sa sa kasala ka	And Market Star
B 000 400 000 BOUNDOO		na sa
P 960 132 320 - BGH:PGO	and aarraat	
14. I hereby certify that the foregoing is true		
Signed Letter &	KEITH E. BUCY Title DIVISION PRO	D. SUPT. Date 9/30/96
(This space for Federal or State office use) Approved by (ORIG, SGD.) ARMANDO A. LOPEZ Title TITLE THE SHOLL BE 10/16/96		
Conditions of approval, if any:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fradulent statements or representaives as to any matter withing its jurisdiction.



