

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-29284
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	NM-192330
7. Lease Name or Unit Agreement Name	NEW MEXICO DF STATE COM
8. Well No.	3
9. Pool Name or Wildcat	INDIAN BASIN UPPER PENN
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4059' GR	

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator 205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter G : 2000 Feet From The NORTH Line and 1650 Feet From The EAST Line
Section 32 Township 21-S Range 23-E NMPM EDDY COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-08-98: MIRU. TIH W/PLUG & SET IN NIPPLE @ 6829'. BLED 480# OFF TBG. LOAD 3 1/2" TBG W/58 BBLS 2% KCL. LOAD BACKSIDE W/1 BBL. ND 3000# TREE. NUBOP & CHOKE MANIFOLD. REL ON/OFF TOOL FR PKR. TOH LD TBG.
4-09-98: REDRESS ON/OFF TOOL. UNLOAD & RACK 215 JTS 2 7/8" TBG.
4-10-98: TIH W/ON/OFF TOOL, X-OVER, 2 7/8" TBG. LD 2 JTS TBG.
4-13-98: LATCH ONTO PKR @ 6820'. TEST ANNULAS TO 500 PSI-OK. REM BOP. REM TBG COLLAR. INSTL TREE. TEST TREE FLANGE TO 2500 PSI-OK. SWAB FL TO 3400'. REM TREE. INSTL BOP. LOAD TBG W/2% KCL FW.
4-14-98: REL ON/OFF TOOL. LD 1 JT TBG. RUN 2 7/8" S.S. NIPPLE & 1 JT 2 7/8" IPC TBG. LATCH ONTO PKR. PMP DN CSG & TEST ON/OFF TOOL TO 500#-OK. NDBOP. NU TREE. TEST TREE TO 2500#-OK. SWAB FLUID IN TBG TO 3400'. TIH W/GAUGE RING TO 6824'. TIH W/EQUALIZER PRONG & EQUALIZE TBG. TBG ON VAC. TIH W/NEW TOOL. FSH PLUG.
4-15-98: ACIDIZE UPPER PENN O.H. FR 6920-6975' W/5000 GALS GAS WELL ACID & FLSH W/2600 GALS DIESEL. FL @ 5300'. WELL FLOWING ON 25# TP. END FL @ 5400'.
4-16-98: TBG PRESS FELL TO 120#. TIE INTO SALES LINE @ 4:00 PM.
4-17-98: RIG DOWN. OPEN WELL ON FULL CHOKE. FTP-350#. COMPRESSOR DOWN. START COMPRESSOR. WELL FLOWING.
5-30-98: ON 24 HR OPT. FLOWING 0 BO, 3 BW, & 1920 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant

DATE 7/20/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY *Jim W. Leake* TITLE District Supervisor

DATE 7-27-98

CONDITIONS OF APPROVAL, IF ANY: