

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION  
Drawer DD  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

1. Type of Well  
☒ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Dakota Resources, Inc. (I)

3. Address and Telephone No.

310 W. Wall, Ste 814, Midland, TX 79701 (915) 687-0800

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter F: 2180' FNL & 1980' FWL  
Sec 7 T-21-S R-28-E

5. Lease Designation and Serial No.

LC-060572A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

BIG EDDY FEDERAL #98  
9. API Well No.

30-015-24707

10. Field and Pool, or Exploratory Area

NW FENTON-DELAWARE

11. County or Parish, State

EDDY, NEW MEXICO

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Estimated starting date: July 21, 1994

MIRU Workover Rig. Dig 10'x10'x8' earthen workover pit on existing well pad to catch any overflow. Tooh w/rods & pump. NU BOPE. Tooh w/ tbg. RIH w/ 4 3/4" bit & DC's. Drill out CIBP @ 3080'. Clean well out to PBTD @3311'. TIH w/ packer & set same @ 3100'± to isolate perforations @ 2942' to 2976'. Swab test perfs 3122-30' & 3145-60' (total 23 shots) to frac tank. Evaluate & frac if required. Put well on production & test intervals 2942-76', 3122-30' & 3145-60'. Cover earthen pit.

14. I hereby certify that the foregoing is true and correct

Signed

*Bryce M. Hulse*

Title

Operations Mgr

Date

6-29-94

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

ENGINEER

Date

7/26/94

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side