## UNITED STATES

N.M. Oil Cons R11 S 1st Street

ivision

CISF

FORM APPROVED

August 1999)	DEPARTMENT OF THE BUREAU OF LAND MANA		ERIOR Artes	ia.	NM 88210-	2834 5. Lease	Expire	1B No. 1004-0135 s November 30, 2000			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						NM-89151  6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRIPLICATE - Other instructions on reverse side						7. If Unit or CA/Agreement, Name and/or No.					
. Type of Well						1					
Oil Well 🛛 Gas Well 🔲 Other				~ 	8. Well Name and No.						
Name of Operator 🗸								Spring ART Federal #1			
Yates Petroleum Corporation				<u> </u>			9. API Well No. 30-015-29825				
a. Address 105 S. 4th St Artesia, NM 88210			b. Phone No. (include 505-748-14	code)	10 Field		UID-29823 ol, or Exploratory Area	_			
Location of Well (Footage, Sec., T., R., M., or Survey Description)			303-740-14	05.740 1472				Strawn, NE (gas)			
	TEL of Section 23-T		-R26E (Unit	0,	SWSE)	11. Count			_		
							Edd	y Co., NM			
12. CHECK AI	PPROPRIATE BOX(ES) T	O IN	IDICATE NATU	RE O	F NOTICE, RI	EPORT, C	OR 01	THER DATA	_		
TYPE OF SUBMISSION	TYPE OF ACTION										
_	Acidize		Deepen		Production (Start	/Resume)		Water Shut-Off			
Notice of Intent	☐ Alter Casing		Fracture Treat		Reclamation			Well Integrity			
Subsequent Report	Casing Repair		New Construction		Recomplete			Other	_		
_ , ,	Change Plans		Plug and Abandon		Temporarily Aba	andon					
Final Abandonment Notice	Convert to Injection	u	Plug Back	u	Water Disposal						
If the proposal is to deepen direction Attach the Bond under which to following completion of the intesting has been completed. For determined that the site is ready	ed Operation (clearly state all perfectionally or recomplete horizonta the work will be performed or provolved operations. If the operational Abandonment Notices shall for final inspection.)	illy, g ovide n resi be file	tive subsurface location the Bond No. on file ults in a multiple comp ed only after all requi	ns and with I pletion	i measured and tru BLM/BIA. Require or recompletion i	ie vertical oc red subseque in a new inte	puns or nt repo rval, a	orts shall be filed within 30 da Form 3160-4 shall be filed or	ays ics		
1. Blow well down	n. If tubing blows	do	wn and won't	со	ntinue to	flow, 1	oad	tubing.			
Nipple down tree a						·		Ü			
2. Unset packer a	t 9241'. POOH wit	h t	ubing and pa	icke	r.						
3. GIH with tubir	ng open ended and s	pot	: 35 sack ceπ	nent	plugs at	9340',	8290	0' and 7690'.			
NOTE: The plug sp	ootted at 9340' mus	t b	e tagged at	923	0' or high	er. If	pl	ug is not			
4. Freepoint 7" o	oth, respot plug an casing. NOTE: Top	of	ag plug. cement is o	calc	ulated to	be at 2	2180	'. Cut and			
pull casing from 5	0' above freepoint	•	. 1		•	. 1		-1 A- £:11			
5. GIH with tubir	ng 50' inside 7" ca	sir	ng stub. Spo	ot a	large eno	ougn cer	nent	plug to 1111			
50' above the stub	o. WOC. Tag plug. ig is not tagged hi	ah.	oneugh recr	ota 8	and re-tag	.aggeu .	00	above the stub			
6. Spot a 100' ce	ement plug (35 sack	gu mi	enough, resp inimum) acros	ss t	he 13-3/8"	casing	sh	oe (419').			
		. 111	CON	PINU	ED ON NEXT	PAGE			=		
4. I hereby certify that the foregoi Name (Printed/Typed)	ng is true and correct										
Rusty Klelin			Title	Tille Operations Technician							
Signature Hustin	Then		Date	Janu	iary 18, 20	000			_		
1 1	THIS SPACE	FOR	FEDERAL OR S	TATE	OFFICE USE				_		
Approved by (OPIG. SG	D.) DAVID R GLASS		arrant or	OL.	eum engin		Date_	JAN 2 5 2000			
ertify			ect lease   O	ffice	O Fra	D. W. C. Care	~				

which Title 1 States Last Well On Lease. Lease NM-89151 Has Been in Its Extended Term By Prduction Since 08-31-1999 And Will Terminate In 60 Days (03-25-2000) Without Operations To Restore Production.

any person knowing and the state of the stat

CECEINED

PE & A HS WAL WAS