

LOWE STATE #3

03/23/98

TMD: 8131 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 07:15 238 A PROBLEMS / DRILL 8023-8050 (27') W/ NO BIT
 JETS /SPOT 150 BBLs LCM PILL ON BOTTOM
 07:15 10:00 238 A PROBLEMS / TOO H FOR BIT JETS /BIT OUT OF
 GUAGE 1/8"
 10:00 11:30 238 A PROBLEMS / TIH W/ NEW BIT AND DRILL COLLARS
 11:30 12:00 09A CUT DRLG LINE
 12:00 14:00 238 A PROBLEMS / FINISH TRIP IN HOLE/ LD 6 JTS
 DP
 14:00 15:00 238 A PROBLEMS / REAMED 186' TO BOTTOM
 15:00 17:00 02A A DRILLING 8050'-8080' (30') ON DAYRATE
 GOOD CIRCULATION
 17:00 20:45 02A A DRILLING 8080-8131 (51') LOST TOTAL RETRUNS
 20:45 22:15 238 A PROBLEMS / PUMP 150 BBLs LCM PILL W/ ACID
 SOLUBLE MATERIALS
 22:15 22:45 238 A PROBLEMS / PULL 10 STDS DP/ BIT 7206'
 22:45 01:30 238 A PROBLEMS / MIX LCM PILL AND BUILD VOLUME
 01:30 02:30 238 A PROBLEMS / PUMP 150 BBL 20#/BBL LCM PILL
 NO PSI
 02:30 05:00 238 A PROBLEMS / MIX LCM PILL AND BUILD VOLUME
 TOO H TO REMOVE BIT JETS

03/24/98

TMD: 8131 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 10:00 238 A PROBLEMS /TRIP TO REMOVE BIT JETS /SET END O
 BIT @ 7200'
 10:00 12:30 238 A PROBLEMS /MIX 150 BBL -40#/BBL LCM PILL
 PUMP SAME / NO INDICATION OF PSI OR FILLUP
 12:30 14:00 238 A PROBLEMS / MIX 150 BBL 40#/BBL LCM PILL
 14:00 15:00 238 A PROBLEMS / PUMP LCM PILL #4- 150 BBLs
 NO PSI
 15:00 17:30 238 A PROBLEMS / MIX 150 BBL 40#/BBL LCM AND
 BUILD VOLUME
 17:30 17:45 238 A PROBLEMS / PULL 5 STDS /END OF BIT-6730'
 17:45 18:30 238 A PROBLEMS / PUMP 150 BBLs 40#/BBL LCM-#5
 NO PSI OR INDICATION OF FILL UP
 18:30 20:45 238 A PROBLEMS MIX 150 BBL 40#/BBL LCM PILL AND CM
 20:45 21:45 238 A PROBLEMS / PUMP 150 BBL LCM PILL (#6)
 21:45 01:15 238 A PROBLEMS / MIX 150 BBL 40#/BBL LCM PILL
 01:15 02:15 238 A PROBLEMS / PUMP 150 BBL LCM (#7) NO PSI AND
 NO MOVEMENT OF FLUID UP HOLE
 02:15 03:15 238 A PROBLEMS / MIX 150 BBL 40#/BBL LCM PILL
 03:15 05:00 238 A PROBLEMS / TIH W/DP TAGGED UP @8066' (FIRM)
 TOO H TO CK FOR FLUID LEVEL