

LOWE STATE #303/18/98

TMD: 7319 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 05:30 23B A PROBLEMS / PUMP 150 BBL 35#/BBL LCM PILL
 NO PSI
 05:30 06:00 23B A PROBLEMS / PULL 5 STDS TO 6800'
 06:00 08:15 23B A PROBLEMS / MIX 150 BBL LCM PILL
 08:15 08:30 23B A PROBLEMS / TIH 5 STDS TO 7300'
 08:30 09:30 23B A PROBLEMS / PUMP 150 BBL 35#/BBL LCM PILL
 NO PSI
 09:30 11:30 23B A PROBLEMS / MIX 150 BBL LCM PILL
 11:30 12:30 23B A PROBLEMS / PUMP 150 BBL 35#/BBL LCM PILL
 NO PSI
 12:30 13:45 23B A PROBLEMS /START MIX LCM PILL
 13:45 19:15 23B A PROBLEMS / TRIP TO REMOVE BIT JETS / SET
 AT 6800'
 19:15 22:30 23B A PROBLEMS / MIX 150 BBL 35#/BBL LCM PILL
 W/MAXI SEAL/COTTONSEED HULLS /CEDAR FIBER
 22:30 23:30 23B A PROBLEMS / PUMP 150 BBL 35#/ BBL LCM PILL
 NO PSI/ SHUT DOWN /ROTATE DP
 23:30 02:15 23B A PROBLEMS / MIX 150 BBL 40#/BBL LCM PILL
 W/ COARSE MATERIALS
 02:15 03:00 23B A PROBLEMS /PUMP 150 BBL 40#/BBL LCM PILL
 REGAIN PARTIAL TO FULL RETURNS
 03:00 05:00 23B A PROBLEMS / C&CM AT 6800'

03/19/98

TMD: 7585 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 08:00 05B A CIRC & COND MUD
 08:00 08:15 23B A TRIPPING 5 STDS TO BOTTOM
 08:15 09:30 02A A DRILLING 10' NEW HOLE /GOOD RETURNS
 09:30 15:30 06A A TRIPPING FOR BIT JETS 3-14'S
 15:30 21:30 02A A DRILLING 7332-7503 (171') LOST RETURNS
 (BACK ON FOOTAGE RATE AT 7275') 17:00 HRS
 21:30 22:30 23B A PROBLEMS PULL 7 STDS DP
 22:30 00:30 23B A PROBLEMS MIX LCM PILL
 00:30 01:15 23B A PROBLEMS PUMP LCM PILL / REGAIN RETURNS
 01:15 01:45 23B A PROBLEMS / TIH W/7 STDS DP
 01:45 05:00 02A A DRILLING 7503-7585 (82') W/ GOOD RETURNS
 (BACK ON FOOTAGE RATE)