

LOWE STATE #303/09/98

TMD: 3466 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 09:00 02A A DRILLING 2703-2879 (176)
 09:00 09:15 10A SURVEYS .25 DEG-2839
 09:15 00:30 02A A DRILLING 2879-3351 (472)
 00:30 01:00 10A SURVEYS .50 DEG-3311
 01:00 05:00 02A A DRILLING 3351-3466 (115)

03/10/98

TMD: 4081 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 18:45 02A A DRILLING 3466-3827 (361)
 18:45 19:00 10A SURVEYS .50 DEG-3787
 19:00 05:00 02A A DRILLING 3827-4081 (254)

03/11/98

TMD: 4675 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 16:15 02A A DRILLING 4081-4367 (286)
 16:15 16:30 10A SURVEYS .50 DEG-4295
 16:30 05:00 02A A DRILLING 4367-4675 (308)

03/12/98

TMD: 5304 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 12:00 02A A DRILLING 4675-4843 (168)
 12:00 12:15 10A SURVEYS 1.0 DEG-4803'
 12:15 04:00 02A A DRILLING 4843-5286 (443)
 04:00 04:15 10A SURVEYS 1.0 DEG-5246
 04:15 05:00 02A A DRILLING 5286-5304 (18)

03/13/98

TMD: 5904 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 22:45 02A A DRILLING 5304-5760 (456)
 22:45 23:00 10A SURVEYS 1.25 DEG-5720
 23:00 05:00 02A A DRILLING 5760-5904 (144)

03/14/98

TMD: 6455 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 20:30 02A A DRILLING 5904-6262 (358)
 20:30 20:45 10A SURVEYS 1.5 DEG-6220'
 20:45 05:00 02A A DRILLING 6262-6455 (193)

03/15/98

TMD: 6957 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 07:30 02A A DRILLING 6455-6514 (59)
 07:30 08:00 10A SURVEYS 2.25 DEG-6474'
 08:00 12:00 02A A DRILLING 6514-6610 (96')
 12:00 12:30 10A SURVEYS 1.25 DEG- 6570'
 12:30 21:00 02A A DRILLING 6610-6830 (220')
 21:00 21:15 10A SURVEYS .50 DEG-6790'
 21:15 02:00 02A A DRILLING 6830-6957 (127')
 02:00 05:00 06A A TRIPPING FOR BIT