Form 3160-5 (November 1994)

## JNITED STATES DEPARTMENT OF THE INTERIOR

N.M. Oil	Cas	Di
811 S. 1st	n at	
011 0 31	~ ~ <del>~ </del>	5.
A	2 00	

FORM APPROVED DIVISION Bureau No. 1004-0 Expires July 31, 1996				2
Divis	<b>i (345)</b> Bur	eau No.	1004-013	35
	Expires .	July 31,	1996	

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		5. Lease Serial No.  14.28347  6. If Indian, Allottee or Tribe Name		
	- Other instructions on reverse sig	de	7. If Unit or CA/A	greement, Name and/or No
1. Type of Well  X Oil Gas Well Other  2. Name of Operator Santa Fe Energy Resources, Inc.  3a. Address 550 W. Texas, Suite 1330, Midland, 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  (K), 2045' FSL and 2200' FWL, Sec.	TX 79701 (915)686-66	(include drea code)	8. Well Name and I Nagooltee Pea Federal #5 9. API Well No. 30-015-30558 10. Field and Pool, Indian Basin Penn) Assoc. 11. County or Paris	or Exploratory Area (Upper
12. CHECK APPROPRI	ATE BOX(ES) TO INDICATE NATU	JRE OF NOTICE, REPORT,	, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION		
Notice of Intent  X Subsequent Report  Final Abandonment Notice	Change Plans Plug and Convert to Injection Plug Bac	e Treat Reclamation Recomplet d Abandon Temporarii ck Water Disp	ly Abandon Se	Water Shut-Off  Well Integrity  Other <u>Spud &amp;</u> It surface csq.
Describe Proposed or Coommpleted Operation (clearl If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. If testing has been completed. Final Abandonment Nodetermined that the final site is ready for final inspection 3/10/99: Spud 12-3/4" hole at 8:  3/13/99: TD 12-3/4" hole (Depth & ST&C casing and set shoe at 161 Celloflake, & 10 pps Gilsonite, 3 200 sx Cl "C" + 2% CaCl2. Bumped did not circulate. Wait on temp	nete norizonatily, give subsurface locations formed or provide the Bond No. on file the operation results in a multiple comple otices shall be filed only after all required.)  1615') at 11:15 a.m. RU c. 15'. Cemented csg w/ 200 s. 180 sx 35:65:6 Poz "C" contiled plug w/500 psi over.	s and measured and true versit with BLM/BIA. Required substition or recompletion in a new rements, including reclamation, as a crew and run 39 cx Cl "H" containing caining 2% CaCl2 & 5	cal depths of all pertibosequent reports shall winterval, a Form 31, have been complete jts 9-5/8" 36 g 10% A-10B, 05 pps Gilsonit	inent markers and zones, be filed within 30 days 160-4 shall be filed once and the operator has 5.0# K-55 LT&C 0.25 pps

3/14/99: WOC for temp survey. RU & run temp svy. Found top of cement at 200'. RU and run 1" pipe to 197'. Cemented w/1st 25 sx Cl "C" + 4% CaCl2. Wait on cmt. Top of cmt at 148'. Cement w/2nd 25 sx Cl "C" + 4% CaCl2. WOC. Cmt w/3rd 25 sx Cl "C" + 4% CaCl2. TOC 200'. Wait on cmt. Cemented w/4th 30 sx C1 "C" + 4% CaC12. TOC 148'. Wait on cmt. Cemented w/5th 25 sx C1 "C" + 4% CaC12. TOC @ 90'. WOC. Cmt 6th 25 sx Cl "C" + 4% CaCl2. TOC @ 73'. WOC. Cement next 4 stages w/25 sx Cl "C" + 4% CaCl2. Cemented w/ 10 stages so far. WOC. TOC @ 64'. ORIG SGD I GARY COURSE

3/15/99: WOC & welder. Cemented 11th stage w/ 35 sx Cl "C" + 2% CaCl2. Ci

rc'd	ACCEPTED FOR RECORD		
lerk		NUR 2 9 1999	

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Terry McCullough

Sr. Production C

3/22/99

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

Date Office

which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Nagooltee Peak 5 Fed. #5 Page 2

3/15/99: Cut off & weld on head, test to 1000 PSI. NU BOP & choke manifold. Test BOP, blind rams, & choke manifold to 3000 PSI, no test on pipe rams. Clean up rams & re-test, would not hold. Fin testing & wait on new rams, hydril test to 1500 PSI ok, all floor valves ok. PU BHA & wait on pipe ram rubbers. Change out ram rubbers.

3/16/99 Change out ram rubbers. Try to test pipe rams, would not test. Wait on welder to build up slides on BOP, build up slides & test to 250 low 300 hi, held ok. PU DCs & RIH. Test csg to 1500 PSI, held ok. Drlg cmt, FC & shoe jt. Resume drlg formation.