¹ Submit 3 Copies to Appropriate	State of New Energy, Minerals and Natural		Form C-103
District Office	LINERY, WILING ALS AND MAULTAI	Resources Department	Revised 1-1-89
DISTRICT I	OIL CONSERVATI	ON DIVISION	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2		WELL API NO. 30-015-30582
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	0 87504-2088	5. Indicate Type of Lease
DISTRICT III			STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. K-4529
SUNDRY NOT	ICES AND REPORTS ON W	ELLS	
(DO NOT USE THIS FORM FOR PRI DIFFERENT RESEI (FORM C	OPOSALS TO DRILL OR TO DEEPE RVOIR. USE "APPLICATION FOR F "101) FOR SUCH PROPOSALS.	EN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
I. IYPE OF WELL:		1378	
OR. CAS WELL X	OTHER		South Avalon ASZ State Co
2. Name of Operator V	A@T ())		8. Well No.
YATES PETROLEUM CORPOR 3. Address of Operator		RECEIVED T	
105 South 4th St., Art	esia, NM 88210	ARTESIA	9. Pool same or Wildcat
4. Well Location		<u></u>	Burton Flat Morrow
Unit Letter :660	Feet From The North	Line and 165	0 Feet From The West
	01 -		
Section 14	Township 21S	Range 26E	NMPM Eddy Com
		60' GR	
11. Check	Appropriate Box to Indicate		when Date
			-
	ENTION TO:	SUB	SEQUENT REPORT OF:
NOTICE OF INT PERFORM REMEDIAL WORK	PLUG AND ABANDON	SUB REMEDIAL WORK	SEQUENT REPORT OF:
		REMEDIAL WORK	
		REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE	ALTERING CASING
		REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti	ALTERING CASING OPNS. PLUG AND ABANDONMEN MENT JOB
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give pertinent dates, includ	ALTERING CASING OPNS. PLUG AND ABANDONMEN MENT JOB
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give pertinent dates, includ Ran 268 joints of 3,36'); 65 joints	ALTERING CASING ALTERING CASING OPNS. PLUG AND ABANDONMEN MENT JOB on casing & cement ling estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16)
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2'' 17# S-95 (1103 # J-55 (1668.25'); 76	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give pertinent dates, includ Ran 268 joints of 3.36'); 65 joints joints of 5-1/2"	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement ling estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103 J-55 (1668.25'); 76 -55 (1080.17') and 34	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, includ Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2"	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement A cement
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give pertinent dates, inclus Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement A cement
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclus Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement ing estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows:
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103) # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at J ass H (61-15-11), 1% s	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, includ Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil	ALTERING CASING ALTERING CASING OPNS. PLUG AND ABANDONMEN MENT JOB on casing & cement Ung estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103) # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at 1 ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4-	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give pertinent dates, includ Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement ing estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, of at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103) # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float st Marker joint set at J ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4- s. Stage 2: 1050 sac	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, includ Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement $\frac{1}{1000}$
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103) # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at 11 ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4-5 s. Stage 2: 1050 sac celloflake and 5#/sack	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclus Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement $\frac{1}{100}$ 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Taile
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103 # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at J ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4- s. Stage 2: 1050 sac celloflake and 5#/sack s H Neat (yield 1.20,	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give pertinent dates, inclus Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement $\frac{1}{100}$ concasing any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pJ
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103) # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at 1 ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4- s. Stage 2: 1050 sac celloflake and 5#/sack s H Neat (yield 1.20, te. WOC. Released ref	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclus Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P ig at 11:00 PM 7-	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement ing estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of $5-1/2"$ 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pJ 4-99. NOTE: On 1st stage,
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS ions (Clearly state all pertinent details, of at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103) # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float st Marker joint set at 1 ass H (61-15-11), 1% st .1). PD 12:40 PM 7-4- s. Stage 2: 1050 sac celloflake and 5#/sacks s H Neat (yield 1.20, te. WOC. Released rf splaced with mud. Wer	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclust Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 k gilsonite (yiel weight 15.5). P ig at 11:00 PM 7- nt 3-1/2 bbls ove	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement ing estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pJ 4-99. NOTE: On 1st stage, r displacement & still did r
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103) # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at J ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4- s. Stage 2: 1050 sac celloflake and 5#/sack s H Neat (yield 1.20, te. WOC. Released ru splaced with mud. Wer d only partial returns	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclust Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P ig at 11:00 PM 7- nt 3-1/2 bbls ove s on last 10 bbls	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement ing estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pJ 4-99. NOTE: On 1st stage, r displacement & still did r of displacement. Waiting
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclust Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P ig at 11:00 PM 7- nt 3-1/2 bbls ove s on last 10 bbls abelief. on completi	ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement And the of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pl 4-99. NOTE: On 1st stage, r displacement & still did r of displacement. Waiting on unit.
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclust Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P ig at 11:00 PM 7- nt 3-1/2 bbls ove s on last 10 bbls abelief. on completi	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement ing estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pJ 4-99. NOTE: On 1st stage, r displacement & still did r of displacement. Waiting
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103 # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at J ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4- s. Stage 2: 1050 sac celloflake and 5#/sacks s H Neat (yield 1.20, te. WOC. Released rd splaced with mud. Wer d only partial returns and complete to the best of my thowledge and and and and and and and and and and and	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclust Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P ig at 11:00 PM 7- nt 3-1/2 bbls ove s on last 10 bbls abelief. on completi	ALTERING CASING PLUG AND ABANDONMENT MENT JOB on casing & cement And the of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pl 4-99. NOTE: On 1st stage, r displacement & still did r of displacement. Waiting on unit.
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclus Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P ig at 11:00 PM 7- nt 3-1/2 bbls ove s on last 10 bbls abelia. On completi me Operations Te	ALTERING CASING PLUG AND ABANDONMEN MENT JOB on casing & cement Ling estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pl 4-99. NOTE: On 1st stage, r displacement & still did r of displacement. Waiting on unit. echnician DATE July 9, 199 TELEPHONE NO. 505/74
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS ions (Clearly state all pertinent details, a at 6:00 PM 7-2-99. H 5-1/2" 17# S-95 (1103 # J-55 (1668.25'); 76 -55 (1080.17') and 34 et at 11200'. Float s Marker joint set at J ass H (61-15-11), 1% s .1). PD 12:40 PM 7-4- s. Stage 2: 1050 sac celloflake and 5#/sacks s H Neat (yield 1.20, te. WOC. Released rd splaced with mud. Wer d only partial returns and complete to the best of my thowledge and and and and and and and and and and and	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Producti and give periment dates, inclus Ran 268 joints of 3.36'); 65 joints joints of 5-1/2" joints of 5-1/2" shoe set at 11200 10572'. Cemented salt, 5#/sack gil -99. Circulated cks Class G (65-3 c gilsonite (yiel weight 15.5). P ig at 11:00 PM 7- nt 3-1/2 bbls ove s on last 10 bbls abelia. On completi me Operations Te	ALTERING CASING PLUG AND ABANDONMER MENT JOB on casing & cement ing estimated date of starting any proposed 5-1/2" 17# & 15.5# casing a of 5-1/2" 17# N-80 (2701.16 15.5# J-55 (3253.77'); 26 17# L-80 (1410.70') (Total '. Float collar set at 1115 in two stages as follows: sonite, .7% FL25, .7% FL52 154 sacks. Circulated thru 5-6), 2% salt, 4/10% FL25, d 2.08, weight 12.4). Tailed D 6:30 PM 7-4-99. Bumped pJ 4-99. NOTE: On 1st stage, r displacement & still did r of displacement. Waiting on unit. echnician July 9, 199