

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-30582
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K-4529
7. Lease Name or Unit Agreement Name	
South Avalon ASZ State Com	
8. Well No.	1
9. Pool name or Wildcat	Burton Flat Morrow
10. Elevation (Show whether DP, RKB, RT, GR, etc.)	
3160' GR	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter C : 660 Feet From The North Line and 1650 Feet From The West Line Section 14 Township 21S Range 26E NMPM Eddy County
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3160' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Commingle Morrow zones <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-13-99 - Moved in and rigged up pulling unit.

10-14-99 - Bled well down. Loaded with 65 bbls 2% KCL. Released packer. Nippled down tree and nipped up BOP. TOOH with packer. TIH with retrieving tool and tagged sand at 10914'. Rigged up swivel and washed down to RBP at 10956'. Circulated clean. Latched onto RBP and released RBP. TOOH with 65 stands. Shut well in.

10-15-99 - TOOH with RBP. TIH with on/off tool, 1 joint 2-3/8" L-80, 10' 2-3/8" sub, 1.875" open sliding sleeve, 20' blast joint, sub, 1 joint 2-3/8" L-80, Uni III packer, 2.25" seating nipple and 343 joints of 2-7/8" L-80 tubing. Tagged packer at 10966'. Could not latch onto before setting Uni III packer. On/off tool should be over seating nipple. Nippled down BOP and nipped up tree. Swabbed Upper Morrow through sliding sleeve. Shut well in.

10-16-99 - Rigged up wireline. TIH with pulling tool for equalizing probe. Could not latch onto. TOOH. TIH with 5-1/2" bailer and bailed off top of plug. Got several pieces of rubber. Marks on bottom of tool shows tagging fishing neck. TIH with pulling

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Oct. 22, 1999  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-14

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

YATES PETROLEUM CORPORATION  
South Avalon ASZ State Com #1  
Section 14-T21S-R26E  
Eddy County, New Mexico


SUNDRY NOTICE CONTINUED:

tool. Did not latch onto - TOOH. Had rubber in tool. Made bailer runs. Closed sliding sleeve. Picked up on tubing and u-tubed out tubing. Latched onto on/off tool. Set down tree. Pressured up on annulus to 500#. Made bailer runs. Had 13' of fill on plug. Shut down.

10-17-99 - Made bailer runs. Had 15' of fill on plug. Set DW plug at 300'. Released on/off tool. Pulled 1 joint and added 4' sub. Washed 4' of sand. Over-displaced tubing with 20 bbls. Latched onto lower packer. Ran slickline with pulling tool. Set down 100' above plug. Worked by but could not latch onto plug. TOOH. Made bailer runs. Nippled down tree and nipped up BOP. Released on/off tool.

10-18-99 - TOOH with BHA and changed out on/off tool and packer. TIH with same BHA. Nippled down BOP and nipped up tree. Washed down 4' to packer. Reversed 100 bbls. Set packer. Rigged up slickline. TIH with equalizer pulling tool. Latched on and pulled equalizing probe. TOOH. TIH with shifting tool and opened sliding sleeve. TOOH. Swabbed tubing. Flowed for 30 minutes. Rigged up slickline. TIH and pulled blanking plug. Flowed well for cleanup. Shut well in.

10-19-99 - Released well to production department.



---

Rusty Klein  
Operations Technician  
October 22, 1999