

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing art out-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Cisco	10031	10043	Minor Gas Show
Strawn	10260	10425	DST recovered 20' gas & distillate cut mud + 340' GCM
Morrow	11070	11282	Tin, low porosity, low perm sands w/minor gas shows
Morrow	11332	11447	Tin sands w/minor gas shows

CONFIDENTIAL

38. GEOLOGICAL MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH
Delaware	2610	
Bone Spring	5032	
Wolfcamp	8067	
Cisco	9586	
Strawn	10156	
Atoka	10520	
Morrow	10934	

38. GEOLOGICAL MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH