Submit 3 Copies To Appropriate District Office District I Energy, Minerals and Na	#7 1 /
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO. 30-015-30855
District III 2040 South Pa	checo STATE FEE [X]
District IV 2040 South Pacheco, Santa Fe, NM 87505 Santa Fe, NM	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.) 1. Type of Well:	R PLUG BACK TO A Pecos "321." Feel Com
Oil Well Gas Well Other 2. Name of Operator Description Community	O W HAY
Devon Energy Production Company, L.1	· OCO COLLAR
Oklahoma City, OK 73102 Ops	Engr. Advisor Avalon (Morrow) (70920]
4. Well Location 405-552-4513	
SHL = Unit Letter L : 1750' feet from the south line and 1250' feet from the west line BHL = Unit Ltr N: 732' FSL & 1894' FWL Section 32 Township 20S Range 27E NMPM County Eddy, NM	
10. Elevation (Show whether GL 3215', DF 3231',	DR, RKB, RT, GR, etc.)
	Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING
PULL OR ALTER CASING MULTIPLE	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND
COMPLETION	CEMENT JOBS
OTHER:	OTHER: workover X
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.	
9-17-2002 thru 10-23-2002 Killed well. ND tree, NU BOP. TOH with packer and tubing. Ran bit and DC's to 10,963'. PU Swivel. Broke circ with air foamer. Cleaned out sand/cement plug. Pushed metal to bottom. Ran BHA to 11,110' PBTD. Circ'd hole clean and TOH. Ran Arrow-Set 5 1/2" packer with 1.87" F nipple on 344 jts 2 3/8" 4.7# N-80 tubing. Set packer at 10,934'. Total 170 BF to keep well killed. Swabbed. RU BJ Srvs. Acidized perfs 10,790-10,990' down tubing with 2000 gals Isosol acid (no BS) at AIR 1.7 BPM with 6250 psi. ISIP 3000 psi, 15 mins 77 psi. Alternately swabbed and flowed. Changed sales line going from compressor to meter run. Well logged off. Swabbed. Returned to sales line for production testing.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Engineering Tech. DATE 11/05/2002 Type or print name Candace R. Graham X4520 Telephone No. (405)235-3611	
(This space for State use)	
APPROVED BY For necessary 15 Bb TIT	LEDATE_NOV 1 3 29