

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
311 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

| | | |
|---|--|--|
| 1. Type of Well Oil <input type="checkbox"/> Gas <input type="checkbox"/> <input checked="" type="checkbox"/> Well <input type="checkbox"/> Well <input type="checkbox"/> Other | 2. Name of Operator STRATA PRODUCTION COMPANY | 5. Lease Designation and Serial No. NM-17103 |
| 3. Address and Telephone No. P. O. Box 1030 Roswell, New Mexico 88202-103 505-622-1127 | 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330' FNL & 1650' FWL Section 25-20S-28E | 6. If Indian, Allottee or Tribe Name |
| | | 7. If Unit or CA, Agreement Designation |
| | | 8. Well Name and No. Lee Federal #8 |
| | | 9. API Well No. <input checked="" type="checkbox"/> 30-015-30862 |
| | | 10. Field and Pool, or Exploratory Area Scanlon Delaware |
| | | 11. County or Parish, State Eddy County, New Mexico |

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | |
|---|---|--|
| <input checked="" type="checkbox"/> Notice of Intent | <input checked="" type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion | <input type="checkbox"/> New Construction |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Plugging Back | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> Water Shut-Off |
| | <input type="checkbox"/> Altering Casing | <input type="checkbox"/> Conversion to Injection |
| | <input type="checkbox"/> OTHER | <input type="checkbox"/> Dispose Water |

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/27/99: Plug and Abandon as approved by Alexis Swoboda with the Roswell BLM.

Set First Plug at 3050' with 50 sacks cement.

Set Second Plug at 2700' with 50 sacks cement.

Set Third Plug at 1150' with 50 sacks cement.

Set Fourth Plug at 475' with 50 sacks cement.

Set Surface Plug at 50' with 20 sacks cement.

12/28/99: Cut off. Install Dry Hole Marker. Release rig at 4:00 PM. Plugged and Abandoned.

Approved as to plugging of the well base,
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed David R. Glass

Title Production Records Manager Dat 03/14/2000

(This space for Federal or State office use)

Approved by REG. SGD. DAVID R. GLASS

Title PETROLEUM ENGINEER

Date MAR 16 2000

Conditions of approval, if any: