Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

υŲ	
ELL API NO.	
30-015-31048	

District Office		_		V	
DISTRICT I	OIL CONSERVATION		WELL ARVAN		
P.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco St.		WELL API NO		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM 87505		30-015-31048 5. Indicate Type of Lease		
			J. Mulcate Typ	STATE X	FEE 🗌
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & C		
7000 Ido Biazos Id., 7/2000, 1414 87410			0. Danie 011 & 0	as Lease No.	
SUNDRY NOTI	CES AND REPORTS ON WE	LLS			ullillilli.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name			
(FORM C	101) FOR SUCH PROPOSALS.)	:RMII"			
1. Type of Well:			NOKIH INDI	AN BASIN UNIT	
OIL GAS WELL X	OTHER				
2. Name of Operator	OTHER		8. Well No.		
Marathon Oil Company			o. Well No.	26	
3. Address of Operator		9. Pool name or Wildcat			
P.O. Box 552 Midland, TX 7	Box 552 Midland, TX 79702		INDIAN BASIN UPPER PENN		
4. Well Location		· · · · · · · · · · · · · · · · · · ·			
Unit Letter F 2210	Feet From The FNL	Line and 165	Feet Fr	om The <b>FWL</b>	Line
Section 16	Township 23 2/ R 10. Elevation (Show wheth	lange 23E		EDDY	County
	10. Elevation (snow wheth	er DF, RKB, RT, GR, etc.)	•		
11. Check An	propriate Box to Indicate		Danaut au (	74b D -4-	
NOTICE OF INT	ENTION TO:	1			
NOTICE OF INT	LATION TO.	20R	SEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANCE DI AND				
	CHANGE PLANS	COMMENCE DRILLING	OPNS.	PLUG AND ABANDO	NMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB		
OTHER:		OTHER: X			
		<u> </u>			
12. Describe Proposed or Completed Opera	tions (Clearly state all pertinent deta	ails, and give pertinent date	es, including estim	ated date of starting any	proposed
work) SEE RULE 1103.					
SEE ATTACHMENT TO FORM C-	102				
SEE ATTACHMENT TO FORM C-	103		13141	516723	
			1273	1979	
			6	<b>→</b> 78/	
			00 00 PEC		
			8 00000		
			200	(Ve) (3)	
			/A		
			/c <sup>2</sup> ;	14 AS	
			100	07.12.5°	
			100	E 56222	
I hereby certify that the information		·····			
I hereby certify that the information above is true	and complete to the best of my knowledge an	d belief.			
SIGNATURE	TITL	E DRILLING ENGINEE	R TECH	DATE <b>5-18</b>	3-00
TYPE OR PRINT NAME TYPE OF PRINT NAME					<del></del>
TYPE OR PRINT NAME JERRY FLETCHER				TELEPHONE NO. 915-6	<u>87-8357</u>
(This space for State Use)		0.		<del></del>	
	<b>\</b>	0.4.4		i i	

CONDITIONS OF APPROVAL, IF ANY:

## **NORTH INDIAN BASIN #36**

2210' FNL & 1650' FWL SEC. 16, T-23-S,R-23-E EDDY CO. N.M.

DRILLED AND SET 40' OF 16" CONDUCTOR PIPE, CEMENT TO SURFACE W/ REDI-MIX.. MIRU MCVAY RIG # 4 , SPUDDED W/ 14-3/4" BIT @ 9:30 AM, DRILLED F/ 40' TO 1215', RAN 27-JTS. 9-5/8" 36# CSG. HALIBURTON CMT W/ LEAD ONE 100 SKS P.P. CMT. (SCAVENGER) W/ 10# /SK DIAMOND SEAL , LEAD TWO, 100 SKS. P.P. THIX-SET W/ 1.0% THIX SET COMP A , .25% THIX SET COMP B , LEAD THREE, 485 SKS, HALAD P.P. W/ 2% CACL2, 5# /SK FLOCELE;5#/SK GILSONITE. TAILED W/ 200 SKS. P.P. CMT. W/ 2% CACL2. PLUG DOWN @ 1400 HRS. T.T. 4/13/00. CIRC. 275 SKS TO SURFACE. WOC 10.5 HRS. PRESSURE TEST CSG. TO 1500 #, DRILL CMT AND FLOAT COLLAR TO 1205'. DRILL 8-3/4" HOLE FROM 1215'TO 8102'. T.D. @ 12:15 HRS. 4-25-00

RIG UP CSG. CREW, RAN FLOAT SHOE, 1-JT. 7" 26# CSG, FLOAT COLLAR, 56 JTS . 7" 26# D.V. TOOL, 23-JTS. 26#. 100 JTS. 7" 23 # AND 1-JT. 26#.

CIRC. HOLE CLEAN, PUMP 50,000 SCF OF N2, 20 BBLS OF NITROFIED WATER AHEAD OF 700 SACKS OF PREMIUM CMT, W/ 350 SCF OF N2 (YIELD 1.44 @ 13-PPG) DISPLACE W/ 98 BBLS WATER AND 215 BBLS MUD. OPEN STAGE TOOL CIRC. 100 SKS.

CEMENT  $2^{ND}$  STAGE W/ 500 SKS. INTERFILL "C" W/ 1/4# FLOCELE, 3# GILSONITE, 2% HALAD 322 ( YIELD 2.47 @ 11.9PPG,

TAILED W/ 100 SKS. PREMIUM PLUS NEAT @ 1.32 @ 14.8 PPG , CIRC. 100 SKS. TEST CSG. TO 1500# RELEASE RIG @ 12:00 NOON C.S.T. 3



