1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 South First, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505					State of New MEALCO Energy Minerals and Natural Resor Oil Conservation Division 2040 South Pacheco Santa Fe, NM 87505						Submit to appropriate District Office State Lease - 6 Copies Fee Lease - 5 Copies			
APPLICATION FOR PERMIT TO DRILL, RE COPERADY NAME and Address POGO PRODUCING COMPANY P.O. BOX 10340 MIDLAND, TEXAS 79702-434								R. DE	EPEN,	PLUGBACK, OR ADD A ZONE 17891 API Number 30- OIS- 31365				
Property Code DAVIS "18						Property Name					*Well No.			
⁷ Surface Location														
UL or los no. Lut #1	Lut # 1 18 20S 27		Range 27E	Lot lån		Foot from the 660 '		!!		Foot from the 660 '	Ens/West line WEST		Carry EDDY	
		Hole	Locatio	ion If Different From Surface										
UL or lot no. Section Town		Township	Range	La	Lation		For from the		South line	For from the	East/West line		Сану	
*Proposed Pool I McMILLIAN-MORROW (81240)								* Proposed Pool 2						
N	N G			F		Cable Rocary ROTARY				" Lease Type Code P		Ground Level Elevanon 3334 '		
Multi NO	1	10,700		MORE		ormation W		EMBR /S	"Councer		Spud Date HEN APPROVED			
NO 10,700 MORROW TMBR/SHARP RIG 23 WHEN APPROVED														
Hole Size Casing Size Casing weight foot								etting D		Sacks of Ce	acks of Cement Estimated TOC			
25"					Conductor		40'			Redi-mix		Surf		
175"		13 3/8"		48			5(650 Sx.		Surf	Surface	
124"		9 5/8"		40.5			2900			1200 Sx.		1	surface	
* 8 ¹ 2" 6 1/8"		7" 5"		7" 26#, 5"		18# 850		00±'		1300 Sx.		T of C 2700'±		
7 7/8"		51/2"		17 & 20		10,7		700 %		1500 Sx		2000'		
 ² Describe the proposed program. If this application is to DEEPEN or PLUG BACK, give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheers if necessary. 1. Drill 25" hole to 40'. Set 40' of 20" conductor pipe and cement to surface with Redi-mix. 2. Drill 17½" hole to 500'. Run and set 500' of 13 3/8" H-40 48# ST&C casing. Cement with 650 Sx. of Class "C" cement + additives, circulate cement to surface. 3. Drill 12½" hole to 2900'. Run and set 2900' of 9 5/8" J-55 40.5# ST&C casing. Cement with 1200 Sx. of Class "C" cement + additives, Circulate cement to surface. 														
 * 4. Drill 8¹/₂" hole to 8500'± if lost circulation becomes a problem that cannot be solved, run and set 7" casing through the lost circulation zones (8500'±). Cement 7" casing with 1000 Sx. of Class "C" cement + additives, estimate top of cement 2000' from surface. Drill out with a 6 1/8" bit to TD (10,700') and run a 5" 18# N-80 from TD to 200' up into the 7" casing. Cement with 300 Sx. of Class "H" cement. 														
5. If no lost circulation is not a problem on reaching 8500' reduce hole to 7 7/8" and drill to TD (10,700'). Run and set 10,700' of 5½" 17 & 20 # N-80 LT&C casing. Cement in 3 stages set DV tools at 8000'± and 6000'±. Cement first stage with 500 Sx. of Class "H" Premium cement, second stage cement with 450 Sx. of Class "C" cement + additives, cement third stage with 550 Sx. of Class "C" cement + additives, all cement volumes depend on caliper logs. Estimate top of final stage cement 2000' from surface.														
¹³ I hereby certify that the information given above is true and complete to the best of my knowledge and belief.								OIL CONSERVATION DIVISION						
Signature: Joel Janing								Approved by: ORIGINAL SHENED BY TIM W. GUNSS						
Priated name: Joe T. Janica								Tide: DISTRICT II SUPERVISOR						
Tide: Agent							Approval Date: OCT 02 2000 Expiration Date: OCT 02 2001							
Date: 09/29,	/00		Phone: 505-391	L-8503		1	Condition Amount		roval:			-		