Form 3160-5 (June 1990)

FORM APPROVED Budget Bureau No. 1004-0135

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT

1301 W. Grand Avenue Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED Budget Bureau No. 1004-0138

Expires: March 31, 1993

1301 W. Grand Avenue Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Artesia, NM 8821/10/Gian. Allottee or Tribe Name

SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
Type of W			27324
Oil Well	Gas Well Dother	2.3.2.	8. Well Name and No.
Name of C	·		ICA 31 Fed No. 1
	d Gussman Permian, L.L.C.	OGRID# 155615	9. API Well No. 30 - 015 - 31587
	nd Telephone No. farienfeld, Suite 508, Midland, TX 7970	n1	10. Field and Pool, or Exploratory Area
	f Well (Footage, Sec., T., R., M., or Survey Desc		Avalon Morrow
	SL & 840' FWL, unit letter L	DOD COLINED	11. County or Parish, State
Sec. 31 -	- T20S - R27E	ARTESIA	Eddy Co., NM
 2.	CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPORT, O	<u> </u>
	TYPE OF SUBMISSION	TYPE OF ACTION	
			Observa of Di
	Notice of Intent	Abandonment	Change of Plans
	Subsequent Report	Recompletion	New Construction Non-Routine Fracturing
	A Subsequent Report	☐ Plugging Back☐ Casing Repair	Water Shut-Off
	Final Abandonment Notice	Altering Casing	Conversion to Injection
		Other upper Morrow completion	☐ Dispose Water
			(Note: Report results of multiple completion on Well
directiona	ally drilled, give subsurface locations and measur	te all pertinet details, and give pertinent dates, including estimated date red and true vertical depths for all markders and zones pertinent to this	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
07/16/01 07/20/01 07/23/01	ally drilled, give subsurface locations and measure. MIRU Pool unit. Bled off pressure. So RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle More with on/off tool. RIH and set packer at	red and true vertical depths for all markders and zones pertinent to this wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Perrow from 10,430' to 10,446' @ 4 SPF. RD Apollo and Pat 10,364'.	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer
07/16/01 07/20/01 07/23/01	ally drilled, give subsurface locations and measure MIRU Pool unit. Bled off pressure. Switch RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Motwith on/off tool. RIH and set packer at 10 RIJ Cudd and acidized Morrow perfs	red and true vertical depths for all markders and zones pertinent to this wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Trow from 10,430' to 10,446' @ 4 SPF. RD Apollo and P at 10,364'.	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer
07/16/01 07/20/01 07/23/01	ally drilled, give subsurface locations and measure MIRU Pool unit. Bled off pressure. Switch RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Motwith on/off tool. RIH and set packer at 10 RIJ Cudd and acidized Morrow perfs	red and true vertical depths for all markders and zones pertinent to this wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Trow from 10,430' to 10,446' @ 4 SPF. RD Apollo and P at 10,364'.	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer
07/16/01 07/20/01 07/23/01 07/25/01 08/02/01	ally drilled, give subsurface locations and measure MIRU Pool unit. Bled off pressure. So RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Mowith on/off tool. RIH and set packer at RU Cudd and acidized Morrow perfs Reset packer at 10,268'. Perforated	red and true vertical depths for all markders and zones pertinent to this wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Perrow from 10,430' to 10,446' @ 4 SPF. RD Apollo and Pat 10,364'.	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer
07/16/01 07/20/01 07/23/01 07/25/01 08/02/01 08/03/01	ally drilled, give subsurface locations and measure MIRU Pool unit. Bled off pressure. So RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Mowith on/off tool. RIH and set packer at RU Cudd and acidized Morrow perfs Reset packer at 10,268'. Perforated Acidized middle and upper Morrow were set to a control of the co	red and true vertical depths for all markders and zones pertinent to this wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Perrow from 10,430' to 10,446' @ 4 SPF. RD Apollo and Part 10,364'. Swith 1300 gals 7.5% NEFE and Nitrogen. Swabbed back the upper Morrow from 10,370' to 10,420' at 4 SPF.	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer
07/16/01 07/20/01 07/23/01 07/25/01 08/02/01 08/03/01	ally drilled, give subsurface locations and measure MIRU Pool unit. Bled off pressure. So RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Mowith on/off tool. RIH and set packer at RU Cudd and acidized Morrow perfs Reset packer at 10,268'. Perforated Acidized middle and upper Morrow were set to a control of the co	wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Perrow from 10,430' to 10,446' @ 4 SPF. RD Apollo and Pat 10,364'. Which with 1300 gals 7.5% NEFE and Nitrogen. Swabbed back the upper Morrow from 10,370' to 10,420' at 4 SPF.	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer k load water but no gas.
07/16/01 07/20/01 07/23/01 07/23/01 07/25/01 08/02/01 08/03/01	ally drilled, give subsurface locations and measure MIRU Pool unit. Bled off pressure. So RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Mowith on/off tool. RIH and set packer at RU Cudd and acidized Morrow perfs Reset packer at 10,268'. Perforated Acidized middle and upper Morrow were set to a control of the co	wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Irrow from 10,430' to 10,446' @ 4 SPF. RD Apollo and Pat 10,364'. Is with 1300 gals 7.5% NEFE and Nitrogen. Swabbed back the upper Morrow from 10,370' to 10,420' at 4 SPF. Sixt with 3000 gallons 7.5% MSR acid and nitrogen. Indicate the series of the se	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer k load water but no gas. abbed APED FOR RECORD NOV - F CARY GOURLEY ETROLEUM ENGINEER
directions 07/16/01 07/20/01 07/23/01 07/25/01 08/02/01 08/03/01 08/06/01	MIRU Pool unit. Bled off pressure. So RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Mowith on/off tool. RIH and set packer at 10 RU Cudd and acidized Morrow perfs Reset packer at 10,268'. Perforated Acidized middle and upper Morrow will RU swab and recovered formation at 10 RU swab and 10 RU	wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Perrow from 10,430' to 10,446' @ 4 SPF. RD Apollo and Pat 10,364'. Which with 1300 gals 7.5% NEFE and Nitrogen. Swabbed back the upper Morrow from 10,370' to 10,420' at 4 SPF.	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer k load water but no gas.
directions 07/16/01 07/20/01 07/23/01 07/25/01 08/02/01 08/03/01 08/06/01	MIRU Pool unit. Bled off pressure. So RU Apollo wireline and set CIBP at 10 RU Apollo and perforated middle Mowith on/off tool. RIH and set packer at RU Cudd and acidized Morrow perfs Reset packer at 10,268'. Perforated Acidized middle and upper Morrow will RU swab and recovered formation and	wabbed back water and gas. 0,469'. Bailed 1 sack cement on top - PBTD at 10,459'. Irrow from 10,430' to 10,446' @ 4 SPF. RD Apollo and Pat 10,364'. Is with 1300 gals 7.5% NEFE and Nitrogen. Swabbed back the upper Morrow from 10,370' to 10,420' at 4 SPF. Sixt with 3000 gallons 7.5% MSR acid and nitrogen. Indicate the series of the se	of starting any proposed work. If well is work.)* U 5½" Arrowset 1-X packer k load water but no gas. abbed APED FOR RECCESTORY CARY GOURLEY ETROLEUM ENGINEER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SOUL AUGS ELL GEROGE LE SOUL AUG SI LO SELL GEROGE LE SOUL AUG SI