	-				~ \7		
Submit 3 Copies To Appropriate District	State of New				C'A	V Form C-	
Office	Energy, Minerals and I	Natura	l Resources		Ч	Revised March 25, 1	999
District I	0.0			WELL AP	I NO.		
1625 N. French Dr., Hobbs, NM 87240 District II		TION	DIVICION		30-015-3	1591	
811 South First, Artesia, NM 87210	OIL CONSERVA			5. Indicate			
District III	2040 South	h Pach	eco	1	··		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, N	VM 87 :	505	STA	ATE 🕱	FEE	
District IV				6. State C	il & Gas I	ease No.	
2040 South Pacheco, Santa Fe, NM 87505				OG-606		<i>Juse</i> 110.	
			<u> </u>			nit Agreement Name:	
SUNDRY NOTICES AND REPORTS ON WELLS [7. (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					vame or U	fut Agreement Name.	
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FOR	1 C-101) FOR SUCH				ļ
PROPOSALS.)	INDIAN HILLS UNIT				г		
1. Type of Well:		•				•	
Oil Well Gas Well	Other		T is				
				8. Well N	0.	· · · · · · · · · · · · · · · · · · ·	
2. Name of Operator			RECEIVED	N. C	0.		
Marathon Oil Company			OCD - ARTESIA	32	11/1		
3. Address of Operator		•	och - Anim	9. Pool na			_
P.O. Box 552 Midland, TX	79702			INDIAN B	ASIN UPP	er penn associatei	2
4. Well Location		•					
			<u>in a sector a sec</u>	660	c . c	.1 1.0706771 1	
Unit Letter	feet from the	5001	H line and	660	feet from	the WEST	ine
Section 16	Township 21 -	-s F	Range 24-E	NMPM		County EDDY	
200000000000000000000000000000000000000	10. Elevation (Show wh			tc.)	8666666666	\$	8882
		4203'	GL-4177'	,			
				Deport (r Other	Data	
	Appropriate Box to Ind	ncate					
NOTICE OF INT	ENTION TO:		SUE	BSEQUE	NT REP	ORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK			ALTERING CASING	i 🗖
					_		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILL	ING OPNS.		PLUG AND ABANDONMENT	
			CASING TEST AND	h			
PULL OR ALTER CASING	MULTIPLE COMPLETION		CEMENT JOB	•			
	COMPLETION						
			OTHER: INITIAL				X
OTHER				CONTRACT TO			لللك

. . .

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

4/12/2001 - MIRU PU & NU BOPS. RIH w/3-1/2" tbg & pickled w/1000 gals. FE acid. Ran correlation log & perfed 8326'-8360' w/4-1/2" TAG guns, 5 jspf @ 60 degree phasing. RIH w/PPI tools & acidize perfs w/100 gpf 15% CCA for a total of 4000 gals. Swabbed well & recovered 202 bbls water, released PPI packer & POOH. RIH w/kill string & RD PU. 5/30/01 MIRU PU, killed well w/160 bbls water. ND wellhead & NU BOPS. POOH w/killstring & RIH w/REP, set @ 5105' & L&T to 500 psi. RIH w/sub pump, landed in wellhead, RD PU. 6/12/01 MIUR PU, ND wellhead & NU BOPS, POOH w/tbg, sub pump & REP. RIH & perfed 8114-8134, 8134-8154, 8166-8186, 8186-8206, 8206-8226, 8234-8244 w/4-1/2" TAG guns, 5 jspf (550 holes). POOH, RIH & perfed from 7870-7972, 7984-7990, 8088-8114 w/5 jspf. RIH, tagged @ 7420', POOH & RIH w/mills, & milled cut hole to 7869'. RIH w/PPI packers to 8246', acidized new perfs w/15% CCA Sour acid, 100 gpf for a total of 26,500 gals. Flowed well back to tank & recovered 36 bbls water, then swabbed well & recovered 65 bbls fluid. Left well flowing w/o pump to test. 6/23/01 POOH w/killstring, RIH w/sub pump on 3-1/2" tbg, set REP @ 8602', ND BOPS & NU wellhead. Start pump & turn over to production department 6/23/01.

		and the second secon	
I hereby certify that the information	above is true and complete to the b	est of my knowledge and belief.	
SIGNATURE Liny	Larke	TITLE Engineer Technician	DATE 7/17/01
Type or print name			Telephone No.
(This space for State use)	ORIGINAL SIGNED BY TIM DISTRICT II SUPERVISOR	W. GUM	AUG 0 9 2081
		_ TITLE	DATE
Conditions of approval, if any:			