Submit 3 Copies to Appropriate District Office				esources Department	CIST	Form C-103 Revised 1-1-89	
P.O. Box 1960 Hobbs, NM 8824	RTESIN	2040 Pach Santa Fe,	eco St.		WELL API NO. 30-015-31926		
P.O. Drawer D. Artesia	10 cu				sIndicate Type of Le		
DISTRICT III 1000 Rio Brazos Rd., Aztec, Q14	9 <sup>3</sup>				₀State Oil & Gas Lea v-3604 ∽	· _ + (	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							
DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7Lease Name or Un	it Agreement Name	
Type of Well:					Lost Tank 35 St	tate	
		OTHER					
aName of Operator Pogo Producing Company					₀Well No. 16		
aAddress of Operator P. O. Box 10340, Midland, TX 797902-7340					Pool name or Wildo Lost Tank Dela		
4Well Location	000						
Unit Letter :	990 Feet F	rom The Nort	<u>in</u>	Line and330	Feet From The	West Line	
Section	<u>35</u> T	ownship 2*	· · ·	ange 31	NMPM	Eddy County	
10Elevation (Show whether DF, RKB, RT, GR, etc.)   3501' GR							
<sup>11</sup> Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO: SUBS					SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING O	PNS. X	PLUG AND ANBANDONMENT	
PULL OR ALTER CASING				CASING TEST AND CEME		L	
OTHER:	· · · · · · · · · · · · · · · · · · ·			OTHER:			

<sup>12</sup>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud & Set Surface Csg - MIRU Patterson #54. Spud well @ 23:30 hrs 02/06/02. Drld 17-1/2" hole to 805'. TD reached @ 03:30 hrs 02/08/02. Ran 18 jts 13-3/8" 48# H-40 ST&C csg. BJ cmt'd w/ 700 sks 65:35 POZ @ 12.8 ppg followed by 200 sks CI "C" + 2% CaCl2 @ 14.8 ppg. Plug down @ 10:30 hrs 02/09/02. Circ 350 sks to surface. WOC 24 hrs. Weld on WH. NU BOP's & test to 1500# ok.

Intermediate Csg - Drld 11" hole to 860'. Lost all returns. Partial returns back @ 880'. Hit wtr flow w/ H2S @ 2725'. Pinched back flow. Cont drilling 11" hole to 4100'. TD reached @ 03:15 hrs 02/14/02. Ran 94 jts 8-5/8" 32# J-55 ST&C csg. Float shoe @ 4100'. Float collar @ 4053'. BJ cmt'd 1st stage w/ 500 sks 65:35 POZ @ 12.4 ppg followed by 200 sks Cl "C" + 1% CaCl2 @ 14.8 ppg. Circ 37 sks to surface. Cmt'd 2nd stage w/ 575 sks 65:35 POZ C @ 12.4 ppg followed by 100 sks Cl "C" + 1% CaCl2 @ 14.8 ppg. Plug down @ 23:45 hrs 02/14/02. Lost all returns just prior to displacing. Never got returns back. Ran temp survey. TOC 110' from surface. Make cut-off. Install WH & test to 1200# ok. NU BOP. Perf 8-5/8" csg w/ 1 hole @ 100'. RU BJ. Could not pump into hole @ 100'. Held 1500# ok. Got call from ARC. TOC @ ±30' from surface. Fill ann to surface w/ cmt. Witnessed by OCD. Test BOP to 3000# ok.

TD & Production Csg - Drld 7-7/8" hole to 8300'. TD reached @ 23:00 hrs 02/21/02. Logged well w/ Baker Atlas. Ran 217 jts 5-1/2" 15.5# & 17# J-55 LT&C csg. Float shoe @ 8300'. Float collar @ 8256'. DV tools @ 5889' & 3802'. BJ cmt'd 1st stage w/ 725 sks Cl "H" + .3% FL52 + .3% CD32 + .15% SMS + .1%R3 @ 15.7 ppg. Circ 175 sks to surface. Cmt'd 2nd stage w/ 625 sks Cl "C" + .15% FL52 + .75% CD32 @ 14.09 ppg. Circ 145 sks to surface. Cmt'd 3rd stage w/ 300 sks 65:35 POZ C @ 12.4 ppg followed by 100 sks "C" Neat @ 14.8 ppg. Circ 16 sks to surface. Plug down @ 03:15 hrs 02/23/02. ND BOP's & make cut-off. Weld on WH. CBL ran 03/08/02. TOC @ surface.

(This space for State Use)	Jim W Sum	District Syn wiser	
TYPE OR PRINT NAME Cathy To	omberlin		TELEPHONE NO. 915-685-8100
SIGNATURE	impert.	TITLE Sr. Operation Tech	DATE 03-21-02