

- Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- O Remote BOP Closing Unit
- □ Sign and Condition Flags

EXHIBIT "D"
RIG LAY OUT PLAT

DEVON-SFS OPERATING, INC.
OLD RANCH KNOWLL "8" FEDERAL # 6
UNIT "G" SECTION 8