




- Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAY OUT PLAT

DEVON-SFS OPERATING, INC.
RIFLEMAN "6-H" FEDERAL COM. # 2
UNIT "H" SECTION 6
T22S-R26E EDDY CO. NM