

- △ H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- O Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT 6 RIG LAY OUT PLAT

OLD RANCH KNOLL "8" FEDERAL SECTION 8 EDDY CO. NM