



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LAND OFFICE _____

LEASE NO. 190903

UNIT _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____		SUBSEQUENT REPORT OF WATER SHUT-OFF _____	
NOTICE OF INTENTION TO CHANGE PLANS _____		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____		SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____		SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____		SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____	X		
NOTICE OF INTENTION TO Plug Back _____	X		

and drill stem test _____
(Indicate above by check mark nature of report, notice, or other data)HIMAPACHE OIL UNIT NO. 3

Hobbs, New Mexico, May 6, 1957

WELL NO. 2 IS LOCATED 2080 FT. FROM {N} LINE AND 2330 FT. FROM {E} LINE OF SEC. 23

23-8 22-E
(TWP.) (RANGE) (MERIDIAN)
Eddy New Mexico
(COUNTY OR SUBDIVISION) (STATE OR TERRITORY)

THE ELEVATION OF THE DERRICK FLOOR ABOVE SEA LEVEL IS _____ FT.

DETAILS OF WORK

(SEE PLANS OF AND DETECTED DEPICTS TO OBJECTIVE SANDS; SHOW SIZES, WEIGHTS, AND LENGTHS OF PROPOSED CASINGS; INDICATE MUDDING JOBS, CEMENTING POINTS, AND ALL OTHER IMPORTANT PROPOSED WORK.)

Set cement plugs from 11,800 to 11,950 feet
10,700 to 10,900 feet
8,360 to 8,560 feet

Drill stem test a zone from 8,190 to 8,360 feet. If nonproductive the well
will be abandoned by setting cement plugs from 6800-6950 feet
2900-3100 feet
15' plug to surface.

I HEREBY CERTIFY THAT THIS PLAN OF WORK MUST RECEIVE APPROVAL IN WRITING BY THE GEOLOGICAL SURVEY BEFORE OPERATIONS MAY BE COMMENCED.

Operator Imperial Oil & Refining CompanyAddress Box 2347Hobbs, N. M.By W. L. SturdevantTitle Agent