

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

AUG 28 1974

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Martin Yates, III		5. State Oil & Gas Lease No.
3. Address of Operator 207 South Fourth Street, Artesia, New Mexico 88210		7. Unit Agreement Name
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 22 TOWNSHIP 23 South RANGE 26 East NMPM.		8. Farm or Lease Name Cordie King
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. 1
		10. Field and Pool, or Wildcat
		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval was given by W. A. Gressett, New Mexico Conservation Commission to plug as follows:

Will pull 7 inch casing

Will spot 25 sacks of cement at bottom of hole, spot 35 sacks of cement at stub of 7 inch ~~base~~, 35 sacks from 500 to 600 feet in and out of surface casing, and set dry hole marker in 20 sacks of cement plug at surface. Intervals between plugs to be filled with heavy mud.

TD 1881
3 7/8" 55' - 100' SX
7" 186' - 50' SX

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Bookkeeper DATE 8-27-74

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE AUG 29 1974

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness

Plugging