

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. **C. C. Staley**, N. Mex., **10/8/27** 19____
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon **Getty-Carlsbad** Well
No. **1** in **NW 1/4** of Sec. **33** of Sec. _____, T. **22 S**, R. **27 E**,
N. M. P. M., **Wild-cat** Oil Field, **Blady** County.
We plan to commence work on **October 13th, 1927**, 19____.

The reasons for wishing to abandon the well are as follows:

Drilled below all known oil zones.

The present condition of the well is as follows:

Depth of well 3137 feet.
Set 160 feet 15 1/2" casing.
Set 653 feet 12 1/2" casing.
Hole full of water.

The work which we propose to do in abandoning the well is as follows:

Will fill hole with heavy mud, mudding off all salt water. On top of mud and above salt water will place wooden plug. On top of wooden plug will dump twelve sacks of cement.

Will leave 15 1/2" casing in hole.

Approved *C. C. Staley* 19 *27*

Except as follows:

A. L. Haller
State Geologist or Oil and Gas Inspector.

Sincerely yours,

George F. Getty Oil Company.

Company or Operator.

By *[Signature]*

Position *[Signature]*

Send communications regarding this well to

Name **George F. Getty Oil Co.**

Address **916 Bartlett Bldg.,
Los Angeles, Calif.**