

Form 9-331a
(Feb. 1951)Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.COPY
(SUBMIT IN TRIPLICATE)Land Office Las CrucesLease No. 061679Unit RECEIVED

APR 3 1961

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1 cy. to 2F.

SUNDRY NOTICES AND REPORTS ON WELLS. C. D.
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 9, 1959

Well No. 1 is located 660 ft. from N line and 660 ft. from W line of sec. 1NW 1/4 Section 1
(1/4 Sec. and Sec. No.) 23 S., 28 E., N.M.P.M.
(Twp.) (Range) (Meridian)Wildcat
(Field) Eddy New Mexico
(County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3065 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

RECEIVED

FEB 11 1959

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

The work performed on this well was as outlined for approval by submission on Form 9-331a under date of October 22, 1958.

On November 9, 1958 a unit was moved over location with which rod and tubing were pulled. Tubing was then rerun and cement plug of ten sacks was placed at depth of 2400 feet. McCullough Tool Company cut 5 1/2" casing off on November 10, 1958 at a depth of 2181 feet. Casing was then pulled and tubing rerun to depth of 280 feet at which depth a plug of ten sacks cement was set. A five sack plug of cement was then set at the surface in the 8-5/8" casing with a regulation marker set in the cement. Pits have been backfilled and location site has been left in an acceptable condition.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Murphy-Lyer Drilling CompanyAddress Box 207Midland, TexasBy /s/ Charles P. MillerTitle Agent