

COUNTY EDDY FIELD Wildcat STATE NM MP 02487, PD
OPR FRANCISCA CORP. MAP

1 Beeman
Sec 2, T-24-S, R-28-E
1980' FSL, 1980' FWL of Sec. CO-ORD

		CLASS			
Spd	8-5-68; Be Camp 2-15-69	FORMATION	DATUM	FORMATION	DATUM
CSG & SX - TUBING					
20"	at 299' w/630 sx				
13 3/8"	at 2509' w/3030 sx				
9 5/8"	at 6253' w/1972 sx				
7" lnr	6105-8146' w/375 sx				
LOGS	EL GR RA IND HC A				
FD 8153' : PBD 6052'					

TEMPORARILY ABANDONED

Distribution limited and publication prohibited by subscribers' agreement.
Reproduction rights reserved by Williams & Lee Sealing Service, Inc.
CONT. Brinninstool PROP DEPTH 9100' TYPE DD
DATE

EDDY
FRANCISCA CORP. Wildcat NM Sec 2, T24S, R28
1 Beeman Page

11-11-68 TD 8153'; CO to 6052'; SD
11-18-68 TD 8153'; CO to 6052'; SD
11-25-68 TD 8153'; CO to 6052'; SD
12-23-68 TD 8153'; CO to 6052'; SD
1-6-69 TD 8153'; CO to 6052'; SD
1-27-69 TD 8153'; CO to 6052'; SD
2-10-69 TD 8153'; CO to 6052'; SD
2-17-69 TD 8153'; PBD 6052'; TEMPORARILY AB
2-20-69 Unable to CO below 6052'
COMPLETION REPORTED

F.R. 9-12-68; OMD; Opr's Elev. 2995' DF
PD 9100' - Wolfcamp
Contractor - Brinninstool
(Orig. Richardson & Bass #1 Julia Beeman et
al, comp. 8-19-54 thru Delaware Perfs 4678-
4684', OTD 8151', OPR 4805')
Depleted Producer 3-15-63
9-16-68 TD 8153'; CO @ 4605'
9-23-68 TD 8153'; CO @ 4800'; SD
9-30-68 TD 8153'; CO @ 4900'
10-7-68 TD 8153'; CO to 5600'; SD Rig Repairs
10-14-68 TD 8153'; CO to 5600'
10-21-68 TD 8153'; CO to 6050'
10-28-68 TD 8153'; CO to 6052'
11-4-68 TD 8153'; CO to 6052'; Milling

EDDY
FRANCISCA CORP.

Wildcat IN Sec 2, 1248, R28
1 Berman 1 ags.

11-11-68	TD 8153'; CO to 6052'; SD
11-18-68	TD 8153'; CO to 6052'; SD
11-25-68	TD 8153'; CO to 6052'; SD
12-23-68	TD 8153'; CO to 6052'; SD
1-6-69	TD 8153'; CO to 6052'; SD
1-27-69	TD 8153'; CO to 6052'; SD
2-10-69	TD 8153'; CO to 6052'; SD
2-17-69	TD 8153'; PBD 6052'; TEMPORARILY AB.
2-20-69	Unable to CO below 6052'

COMPLETION REPORTED