

Francisca Corp. #1 Geeman NESW 2-245-28e

8-17-70 1:50 PM. 1-500 bbl Tank approx 2' fluid - sepr. 1-200 bbl test Tank

Well open @ surface small amount of salt water going up it.
(No change since last visit) 2" flow line from well to Tanks

8-31-70 2:25 PM. 8" collar w/ about 8" piece of cog w/ plate welded on top
w/ 1" welded in + 1" Valve - closed. collar just set on head
Threads don't match - so it leaks - 2" Valve on side of head
open + water coming out -.

9-14-70 2:07 PM. No change since 8-31-70 still leaking

9-28-70 2:30 PM. Well is now closed in. plate welded on top
of Head w/ 1" Valve in it. Valve on side of head closed.
~~water~~ Water down in collar must have been done a few days
back - someone has been in since the rain.

While I was out Mr. Tom Neely in Carlsbad called to tell us
he had closed the well in on 9-26-70

@ 1:30 PM. 9-29-70 Stanley called to see if OK.