

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OCT - 2 '89

WELL API NO.

30-015-02494

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Malaga Unit TR-4

8. Well No.

1

9. Pool name or Wildcat

Malaga Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER Water Injection

2. Name of Operator

The Eastland Oil Company

3. Address of Operator

Drawer 3488, Midland, Texas 79702

4. Well Location

Unit Letter B : 330 Feet From The North Line and 1650 Feet From The East Line

Section 13 Township 24S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

2963' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing in well consists of:

A.- 10 3/4" surface casing @ 280' cemented w/180 sx. & Circ.

B.- 5 1/2" Production set @ 2700' cemented w/100 sx. T.D. is 2748'
completed in open hole.

Plugging Procedure:

1. Spot 25 sx w/2% CAC1 @ 2748' & tag.
2. Load hole with mud laden fluid & cut 5 1/2" csg. @ 1750' +/-.
3. Spot 35 sx inside & out of stub.
4. Spot 35 sx across top of salt & bottom of surface pipe @ 330'.
5. Spot 10 sx surface.
6. Cut off head & install marker, clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Travis Reed*

TITLE Production Superintendent DATE 9-29-89

TYPE OR PRINT NAME Travis Reed

TELEPHONE NO. 683-6293

(This space for State Use)

APPROVED BY

Johnny C. Hansen

TITLE

OIL AND GAS INSPECTOR

DATE 10-5-89

CONDITIONS OF APPROVAL, IF ANY: