

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-101
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR A WELL IN A STEADY STATE RESERVOIR.

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER: **Water Injection Well**

2. Name of Operator: **Austin Gas Purchasing, Inc.**

3. Address of Operator: **Box 159, Stafford, Kansas 67578**

4. Location of Well:
UNIT LETTER **H** **1650** FEET FROM THE **North** LINE AND **330** FEET FROM
THE **East** LINE, SECTION **13** TOWNSHIP **24S** RANGE **28E** N.M.P.M.

5. Elevation (Show whether BP, RT, GR, etc.): **2955' GL**

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.:

7. Unit & Lease Name: **Malaga Unit**

8. Part of Lease Tract: **Tract 9**

9. Well No.: **2**

10. Field and Pool, or similar: **Malaga Delaware**

12. County: **Eddy**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Upon notification from New Mexico Oil & Gas Commission of approval to plug this well. It was plugged by Casing Services and Salvage of Hobbs, New Mexico and the following procedure was used.

10-6-76 Rig up, run tubing to 2550 feet, pump 25 sacks cement, pull tubing, set jacks, shut down.

10-7-76 Rig up wire line truck, shot casing at 1745 feet, pull 57 joints, run tubing to 1800 feet, displace hole with jell, shut down.

10-8-76 Pump 35 sacks cement plug, pull tubing to 364 feet, pump 35 sacks cement, pull tubing, ~~set dry hole marker~~, pump 15 sacks cement for top plug, set dry hole marker, rig down.

Pump jack, cement blocks have been hauled from location. As soon as all casing has been removed, location will be ripped and leveled to its original contour.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: *Robert J. Hunter* TITLE: _____ DATE: 11-4-76

APPROVED BY: *John G. Morris* TITLE: _____ DATE: _____

CONDITIONS OF APPROVAL, IF ANY:

POSTED
11-12-76
11-14-76