

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other instruct.
verse side)CATE*
on re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

M-063736

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

Wagonwire Unit

8. FARM OR LEASE NAME

Wagonwire Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Chaparral Area Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASection 17, T-23-S, R-23-E
MMP Survey

12. COUNTY OR PARISH

Bdry

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ <u>Abandon</u>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Shell Oil Company</u>		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 1858, Roswell, New Mexico 88201</u>		9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>1900' TBL & 1900' TBL (NE 1/4 Sec 17, T-23-S, R-23-E, MMP Survey, Bdry County, New Mexico)</u>		10. FIELD AND POOL, OR WILDCAT
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>2110' DF</u>		12. COUNTY OR PARISH
		13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As propose to set the following plugs:

9600' - 9500'	35 in Inscr
8600' - 7900'	35 in Inscr
7300' - 7200'	35 in Inscr
6400' - 6300'	35 in Inscr
4900' - 4800'	35 in Inscr
3400' - 3200'	70 in Inscr
2700' - 2600'	35 in Inscr
2050' - 1950'	35 in Inscr
Surface	10 in Inscr

Set prescribed markers.

RECEIVED

JUN 25 1964

O. C. C.
ARTESIA, OFFICEVerbal approval obtained June 13, 1964, by R. D. Vassar, Shell Oil Company, from
R. L. Beckman, U.S.G.S.

18. I hereby certify that the foregoing is true and correct

Original Signed By
SIGNED R. J. Deubek
R. J. DeubekDIVISION
TITLE Mechanical Engineer

(This space for Federal or State Police use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:JUN 24 1964
RONNIE E. SHOOK
ACTING DISTRICT ENGINEERTITLE
DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.