October 16, 1968

Union Oil Company of California P. O. Box 671 Midland, Texas

Attention: Mr. George Coombes

Re: Dark Canyon State Com Well No.1-J, 30-23-25, Eddy County, New Mexico

Dear Mr. Coombes:

On August 7, 1968, Mr. James Allen and Mr. Coy Cox, Union Oil Company engineers, and myself inspected the subject well to check a gas leak at the well head. Said inspection revealed that the gas was leaking from a poorly made up union and that the gas was apparently coming from the 13 3/8 casing annulus.

At that time I was advised that a report would be filed pinpointing the source of the gas in the casing annulus. To date this report has not been received.

On September 9, 1968, I wrote Mr. Allen about this matter. No reply has been received, however, it is possible that my letter was sent to the wrong office.

Please check into this matter and advise this office as to what efforts have been made to locate the source of the gas in question.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets Geologist Uniton Of Construction (2011) Entraile (2011) Hox (2017) (2015) Entraile

and the second second states of

の日本では、1955年により、1955年によります。 1955年により、1

्रिक सुरुद्धि है । सुरुद्ध स्त्री

\_\_\_\_\_\_u there is the distribution and the second to the second of a Company support to the second the second the distribution a strained at the second of the second of the second of the second was leaking from a reaction and the representation of the second of entity conting from the second of the basis and the second.

At the star star should be a should be a survey to be (1 b) should be a should be should be a should be a should be a should be a should b

A - Cá za anilit de l'astronament dans que i comi dende de pais.
A - Cára - Cí zapenna (company) ado substance de l'emai analiana antenna.

n par san nga pina ngawan

ALE COMON DEPOSITERADO - COL

y, t, the second of the secon