

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Branson Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-10872
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Guy A. Reed
8. Well No. 1
9. Pool name or Wildcat Malaga Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER
2. Name of Operator Dinero Operating Company
3. Address of Operator P. O. Box 10505, Midland, Texas
4. Well Location Unit Letter <u>E</u> : <u>1,980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>24</u> Township <u>24 South</u> Range <u>28 East</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 2,948' G.R.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up Workover unit, pull rods and tubing out of well.
5 1/2" casing set at 2,645'. Top of cement behind 5 1/2" casing is 1,822'.
Set CIBP at 2,550', spot 35 sacks cement on top, circulate hole w/mud, cut 5 1/2" casing at 2,000', pull out of hole. Go in with tubing and spot 35 sacks cement on top of cut off. Tag cement. Pull tubing out of hole, spot 40-60 sacks 50' below 8 5/8" and bring to surface. Install Dry Hole marker.

Plugging mud to be Salt Gel mud consisting of 10 # brine w/25 # of gel / barrel.

Notify OCD to Witness Tags

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlie Williams TITLE Production Superintendent DATE 2/12/96

TYPE OR PRINT NAME Charlie Williams

TELEPHONE NO. 915/684-5544

(This space for State Use)

APPROVED BY Jim W. Brown TITLE District Supervisor DATE 2-13-96

CONDITIONS OF APPROVAL, IF ANY:

Faxed on 2-13-96 to Dinero's office.
684 3990

Dinero Oper. Co.
Guy Reed 1
24-24-28
Sedco Co., N.M.
BGA
2/13/96

