

WORKOVER REPORT

LEASE ROCK TANK UNITWELL NO. 1JOB NO. AF #309-0058DATE COMPLETED MAY 1974

DATE	WORK DONE
1974 5/1	<p>4362-76 heavy corr 4435 pits 4475 heavy corr</p> <p>Now GIH w/ overshot.</p>
5/2	<p>Changed out tubing cplgs; went in hole w/ overshot; latched on fish; Could not release on-off tool. POH, tbg had unscrewed leaving 3 Jts. tbg, overshot & bumper sub in hole; believe mud & sand has fallen down around on-off tool. Will wash over 194.3' fish & try to re-release on-off tool.</p>
5/3	<p>Ran tubing, screwed into fish & released overshot. Started out of hole & pulling unit broke down.</p>
5/4	<p>Pulled overshot; Went in w/ 210' x 4½" OD x 3 7/8" I.D. wash pipe, DCs and jars; washed over 162' of 194' fish, getting mud, sand & crud. Pulled 4 stands & SD for nite;</p>
5/5	<p>Washed over rest of fish; last 25' drilled very hard getting up sand & scale; Circ clean & pulled out; Went in w/ overshot & jars; Unable to release on-off tool. Pulled 10 stands & SD; Fish looking up in sleeve which is open; Plan to pull overshot & go in w/ BP & Pkr to squeeze csg leak.</p>
5/6	<p>Prep to finish pulling tubing & cmt casing.</p>
5/7	<p>Pulled out of hole & had sleeve, 6 Jts. tubing & on-off tool; PU Model C BP & Pkr; Ran 75 stands & set BP @ 4715 & pulled one stand; Set Pkr & pressure tested to 1500 psi; Set Pkr @ 4030'; Pressured Csg & BOP rubber started leaking; Opened Bradenhead valve & bled off gas in 25 Mins.; Pumped 125 Bbls. Wtr down tubing & circulated out 8 5/8" Csg @ 3 BPM @ 550 to 700 psi;</p>
5/8	<p>Ran Baker Model "K" Cmt retainer, set @ 4030'; Pressured tested casing above Pkr to 1500#; OK & tubing to 2500#, OK; Broke circ & pumped FW ahead of 500 Sx. Class "H" Cmt; Had good circulation thruout; Squeezed last 15 Bbls. Cmt to 850 psi; Reversed out & pulled out of hole; Started in w/ bit & SD for nite.</p>
5/9	<p>Finished GIH w/ tubing & bit; Drilled 3' Cmt & retainer in 3½ Hrs; Hard Cmt to 4235'; Closed BOP & pressured to 1400 psi & held OK; Circulated hole clean & POH; SD overnite.</p>
5/10	<p>Retrieved B.P.; Went in w/ one jt wash pipe, washed over on-off nipple & cleaned hole; Started in hole w/ on-off tool, blast jt & sleeve open & SD for nite.</p>