

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN "PLICATE"
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N. M. 059251

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

North White City Unit

8. FARM OR LEASE NAME

North White City Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC. T. R. M. OR BLM. AND
SURVEY OR AREA

Sec. 31, T-23-S, R-26-E

12. COUNTY OR PARISH

Eddy

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Humble Oil & Refining Co.

3. ADDRESS OF OPERATOR

Box 1600, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface1980' FWL & 960' FNL, Sec. 31, T-23-S, R-26-E,
Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, BS, CR, etc.)

3766

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Plug & Abandon ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled to a total depth of 11,500' and found to be dry.
5439' 8 5/8" csg. set at 5461'.
1360' 11 3/4" csg. set at 1385'.
30' 20" csg. (Conductor Pipe) set at 43'.

Set Plug No. 1 from 11,350' to 11,200' w/40 sacks Class "C" Neat Cement.
Set Plug No. 2 from 10,560' to 10,410' w/40 sacks Class "C" Neat Cement.
Set Plug No. 3 from 9,800' to 9,650' w/60 sacks Class "H" Neat Cement.
Set Plug No. 4 from 8,500' to 8,400' w/40 sacks Class "H" Neat Cement.
Set Plug No. 5 from 6,800' to 6,700' w/40 sacks Class "H" Neat Cement.
Set Plug No. 6 from 5,560' to 5,360' w/80 sacks Class "H" Neat Cement.
Set Plug No. 7 from 2,300' to 2,200' w/40 sacks Class "H" Neat Cement.
Set Plug No. 8 from 500' to 400' w/40 sacks Class "H" Neat Cement.
Set Plug No. 9 from 35' to 5' w/10 sacks Class "H" Neat Cement.

Install dry hole marker.
Clean and level location.

Note: Above plugging procedure approved by Mr. Knauf in telephone conversation with Mr. Ewing on July 16, 1968.

DFL/hn

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE July 23, 1968

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Orig. & 4cc: USGS, Artesia, N.M.; cc: Mr. C. S. Valder, Box 1410, Fort Worth, Texas
cc: Mr. Ed Staley, Box 68, Hobbs, N.M.; cc: Mr. W. J. Henry, Union Oil Co., 300 Security
Nat'l Bk., Roswell, N.M.; cc: J. Braden, 1500 Wilco Bldg., Midland, Texas;
cc: M. A. Sparks, Box 2880, Dallas, Texas; cc: Central File; cc: Hobbs District