Form 9-331 Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Form Approved. Budget Bureau No. 42-R1424 5. LEASE NM 0405444-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS DOMEDWELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME	
1. oil gas well other MAR 29'89	 8. FARM OR LEASE NAME Todd "26" Federal 9. WELL NO. 	
 2. NAME OF OPERATOR Devon Energy Corporation (Nevada) 3. ADDRESS OF OPERATOR	l 10. FIELD OR WILDCAT NAME Sand Dunes (Atoka)	
 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE:1980' FNL & 1980' FEL AT TOP PROD. INTERVAL: Same 	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREASec.26-T23S-R31E12. COUNTY OR PARISH Eddy13. STATE New Mexico	
AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3437 GR	
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)	

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- Attempted to run sinker bars and CCL in tbg. Got down to 9300 ft. Stuck tool. Had to cut off wireline. Tbg & csg annulus were in communication. Circulated 730 bbls 10 ppg brine and killed well. Removed tree. No tbg. Installed BOP's. Ran lead impression block. Found tbg 20 ft down hole. Ran spear, caught tbg and came out of hole w/295 jts 2 7/8" tbg. Tbg badly corroded, appeared to be from carbon dioxide.
- 2. Spent next 8 days fishing tbg and wireline from hole. Recovered all of it. Ran csg inspection log. Ran rental string of tbg, stabbed into pkr and swabbed well in. Ran production log. Left rental string in hole with well producing while getting new string of tbg internally coated. Killed well.
- Ran 418 jts. of TK-99 internally coated 2 7/8" N-80 grd EUE 6.5# tbg. w/nickel coated Baker seal assembly. Circulated hole w/corrosion fluid & bacteriacide. Stabled into packer Loaded hole w/nitrogen and kicked well off.
 Subsurface Safety Valve Manu. and Type Ft.

18. I hereby certify that the foregoing is t	true and correct		
SIGNED	TITLE District Engineer C	DATE3/20/89	
(This space for Federal or State office use)			
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE COUV	DATE	
4. Returned to production.	001 HA VE () - 15 AAI	ACCEPTED FOR RECORD	

•See Instructions on Revose side

MAR 2 71989

SJS CARLSBAD, NEW MEXICO