

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-101
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-20288
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	19003
7. Lease Name or Unit Agreement Name	Allen
8. Well No.	001U
9. Pool name or Wildcat	Carlsbad Strawn, South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Sabre Operating, Inc.	
3. Address of Operator P.O. Box 4848 Wichita Falls, TX 76308-0848	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 31 Township 22S Range 27E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3187' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11300'-11261' CIBP+4sx.
- 10200'-10161' CIBP+4sx.
- Circ. Hole With 10# Salt Water Gel.
- 9068'-8833' 25sx. Class "H" (Tag w/Tbg.)
- 8066'-7829' 25sx. Class "H"
- 5420'-5183' 25sx. Class "H"
- 4050'-3950' 45sx. Class "H" 50' in 50' out 5 1/2" Stub. (Tag w/Tbg.)
- 3040'-2910' 45sx. Class "H" (Tag w/WL)
- 2650'-2466' 45sx. Class "H" 8-5/8" Shoe (Tag w/WL)
- 1137'-1067' 75sx. Class "H" 50' in 50' Out 8-5/8" Stub (Tag w/Tbg.)
- 400-322' 100sx. Class "H" 12-3/4" Shoe (Tag w/Tbg.)
- 30'-3' 25sx. Class "H" Surface
- Install Dry Hole Marker

Post ID-2
6-6-97
PLA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frelan Fields TITLE Agent DATE 5/13/97
Frelan Fields (915) 366-1852
TELEPHONE NO.

(This space for State Use)

APPROVED BY Pher Zappa TITLE FO DATE 6-11-97
CONDITIONS OF APPROVAL, IF ANY: