	Form C-103	
NO. OF SOPIES REALIVED RECEIVED	Supersedes Old C-102 and C-103	
SANTA FE . NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65	
FILE NOV 3 0 1970		
U.S.G.S.	5a. Indicate Type of Lease State X Fee	
LAND OFFICE	5. State Oil & Gas Lease No.	
OPERATOR	L -1902	
ARTESIA, DEFIDE		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name	
I. OIL GAS X OTHER-		
2. Name of Operator	9. Farm or Lease Name	
TEXACO Inc.	N.M. 'DD' State Com.	
3. Address of Operator	9. Well No.	
P.O. BOX 728 - HOBBS, NEW MEXICO 88240		
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER G 1655 FEET FROM THE North LINE AND 2310 FEET FROM	Undesignated	
THE East LINE, SECTION 32 TOWNSHIP 24S RANGE 26E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
3415' GR	Eddy	
<sup>16.</sup> Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING	
PULL OR ALTER CASING		
OTHER	<u></u>	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any proposed	
Subject well has been plugged and abandoned as follows:		
Subject well has been plugged and abandoned as follows: 1. Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000	D#. Re-squeezed	
Subject well has been plugged and abandoned as follows: 1. Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.		
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> </ul>		
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>Loaded hole w/11.5 ppg mud.</li> </ul>		
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>1. Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>2. Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>3. Loaded hole w/11.5 ppg mud.</li> <li>4. Cut off and pulled 7-5/8" casing @ 1545'.</li> </ul>		
<ol> <li>Subject well has been plugged and abandoned as follows:</li> <li>Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>Loaded hole w/11.5 ppg mud.</li> <li>Cut off and pulled 7-5/8" casing @ 1545'.</li> <li>Spotted 100 sx Class C cement w/2% Cacl from 1540' to 1310'.</li> <li>Spotted 50 sx Class C cement w/2% Cacl from 90' to surface.</li> </ol>	from 7975'-7935'.	
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>1. Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>2. Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>3. Loaded hole w/11.5 ppg mud.</li> <li>4. Cut off and pulled 7-5/8" casing @ 1545'.</li> </ul>	from 7975'-7935'.	
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>Loaded hole w/11.5 ppg mud.</li> <li>Cut off and pulled 7-5/8" casing @ 1545'.</li> <li>Spotted 100 sx Class C cement w/2% Cacl from 1540' to 1310'.</li> <li>Spotted 50 sx Class C cement w/2% Cacl from 90' to surface.</li> <li>Installed 4" marker extending 4' above ground level and clean</li> </ul>	from 7975'-7935'.	
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>Loaded hole w/11.5 ppg mud.</li> <li>Cut off and pulled 7-5/8" casing @ 1545'.</li> <li>Spotted 100 sx Class C cement w/2% Cacl from 1540' to 1310'.</li> <li>Spotted 50 sx Class C cement w/2% Cacl from 90' to surface.</li> <li>Installed 4" marker extending 4' above ground level and clean</li> </ul>	from 7975'-7935'.	
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>Loaded hole w/11.5 ppg mud.</li> <li>Cut off and pulled 7-5/8" casing @ 1545'.</li> <li>Spotted 100 sx Class C cement w/2% Cacl from 1540' to 1310'.</li> <li>Spotted 50 sx Class C cement w/2% Cacl from 90' to surface.</li> <li>Installed 4" marker extending 4' above ground level and clean</li> </ul>	from 7975'-7935'.	
<ul> <li>Subject well has been plugged and abandoned as follows:</li> <li>Squeezed perforations 9933-9960' w/50 sx Class C cement to 4000 w/50 sx Class C cement to 3000#.</li> <li>Ran and set bridge plug @ 7975'. Spotted 10 sx Class H cement</li> <li>Loaded hole w/11.5 ppg mud.</li> <li>Cut off and pulled 7-5/8" casing @ 1545'.</li> <li>Spotted 100 sx Class C cement w/2% Cacl from 1540' to 1310'.</li> <li>Spotted 50 sx Class C cement w/2% Cacl from 90' to surface.</li> <li>Installed 4" marker extending 4' above ground level and clean</li> </ul>	from 7975'-7935'.	

5

÷

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W Margan	District Superintendent	DATE November 25, 1970
APPROVED BY O. J. Haun	TITLE OIL AND GAS INSPECTOR	DATE 6-17-71

CONDITIONS OF APPROVAL, IF ANY: