

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-20423
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-120
7. Lease Name or Unit Agreement Name Medano VA State
8. Well No. 1
9. Pool name or Wildcat Undes. Delaware/Bone Springs
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3358' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	Convert to Dual Producer & SWD
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	

4. Well Location Unit Letter <u>K</u> : <u>1947</u> Feet From The <u>South</u> Line and <u>1986</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>23S</u> Range <u>31E</u> NMPM Eddy County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <u>Propose to dual well</u> <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Propose to convert well to SWD in Bone Springs 8065-8639' and producer in Bell Canyon 4218-4237' and Brushy Canyon 7825-7856' as follows: Pull pump and rods. Kill well. TIH with retrieving tool. unseat RBP at 8000' and TOOH. RIH with packer, crossover and 2-7/8" tubing to 8000'. Set packer and acidize Bone springs 8065-8639' w/12600 gals 15% NEFE acid. Run step rate test.

Unseat packer and TOOH. TIH with nickle plated Uni VI injection packer, 2-7/8" plastic-coated tubing. Set packer and inject produced water to confirm that packer is set and holding. Hang injection tubing off and NU BOP. TIH with sub, perforated sub, seating nipple and 2-7/8" production tubing. Sting into parallel string anchor and pull 10 points tension. Hang production tubing off and NU remainder of wellhead equipment. Run pump and rods in hole and put well on pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 2-21-91
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
APPROVED BY ORIGINAL SIGNED BY DATE FEB 28 1991
CONDITIONS OF APPROVAL, IF ANY: SUPERVISOR DISTRICT TITLE