

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. -----
7. Unit Agreement Name -----
8. Farm or Lease Name Randall
9. Well No. 1
10. Field and Pool, or Wildcat So. (Carlsbad) Canyon
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Morris R. Antweil 3. Address of Operator Box 2010, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER <u>K</u> <u>1864</u> FEET FROM THE <u>South</u> LINE AND <u>2005</u> FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>22-S</u> RANGE <u>27-E</u> NMPM.	15. Elevation (Show whether DF, RT, GR, etc.) 3120' GR
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P & A as follows:

1. Spot 15 sx. cement plug on bridge Plug @ 10,100'.
2. Spot 25 sx. cement plug across perms @ 9930'.
3. Cut and pull estimated 6000' 7" casing.
4. Spot 40 sx. cement plug across 7" casing stub.
5. Spot 45 sx. cement plug across 9-5/8" casing shoe @ 5445'.
6. Cut and pull estimated 1500' 9-5/8" casing.
7. Spot 80 sx. cement plug across 9-5/8" casing stub.
8. Spot 85 sx. cement plug across 13-3/8" casing shoe @ 375'.
9. Spot 10 sx. surface plug w/marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R M Williams</u>	TITLE <u>Agent</u>	DATE <u>3 March 1976</u>
APPROVED BY <u>W A Lucero</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>MAR 4 1976</u>
CONDITIONS OF APPROVAL, IF ANY: <u>Intentional 1.5 times larger field volume</u>		