

GULF FEDERAL NO. 2
1980' FSL & 990' FWL
Sec. 6, T-23-S, R-27-E
Eddy County, New Mexico

WORKOVER:

- 12-01-75 Rigging up pulling unit
- 12-02-75 Pumped 50 bbls. KCL down tbg. on Strawn zone - Maximum pressure 500# & went on vacuum - Pumped 50 bbls. KCL down Morrow zone - First 25 bbls. @ 500# & last 25 bbls. @ 3300# - Removed well head & installed BOP'E - Pulled 316 jts. of 2-1/16" tbg. from Strawn zone & worked packer, but could not work free - Shut down for night - Now prep to pull packer & pull Morrow zone tbg.
- 12-03-75 14 hour S.I. 2000# - Blew well down, no fluid - Morrow zone dead - Worked stuck pkr. w/no results - Ran tbg. back into pkr. @ 10,298' - Strawn zone started gassing - Loaded hole w/50 bbls. KCL - Worked top packer loose - Pulled 3 stands tubing & removed BOP - Worked long string & came off at on/off tool - Now prep to pull long string less Lock-Set pkr.
- 12-04-75 Strawn zone 25#, blew down to 0# - Morrow zone dead - Started out of hole w/long string & well started gassing - Dumped 25 bbls. KCL down hole - Pulled 320 jts. 2-1/16" tubing + pkr. & 29 jts. 2-3/8" & laid down 2-3/8" & 2 blast joints & on/off tool - Ran back w/2-1/16" tbg. w/on/off tool & latched in pkr. @ 11,311' - Worked pkr. 2-1/2 hrs. w/no results - Shut down for night.
- 12-05-75 Worked pkr. w/no results - Ran free point to 11,415' tubing free to 11,338' - Pkr. stuck @ 11,340' - Came out of hole w/60 stands of 2-1/16" tbg. & shut-down for night.
- 12-06-75 Pulled 2-1/16" tubing out of hole & picked up 2-3/8" tbg. & wash over shoe & shut down for night.
- 12-07-75 Picked up 2-3/8" & 2-7/8" tbg. & drilled out top ring on Lock-Set pkr. & shut down for night.
- 12-09-75 Ran on/off overshot on 2-3/8" tbg. - Jarred on Lock-Set pkr. for 3 hours w/no results - Left 17 points tension - Prep to wash over packer
- 12-10-75 Came out of hole & picked up wash pipe - Prep to start milling on pkr.
- 12-11-75 Washed over Baker Lock-Set pkr. @ 11,320' - Pulled tbg. & wash over pipe & shoe - Prep to pick up overshot & jars.
- 12-12-75 Ran overshot & jars - Latched onto fish with 100,000# & moved fish up hole 2' - Pulled & jarred 3-1/2 hours, but failed to come loose - Released overshot & started out of hole - Shut down for night
- 12-13-75 Finished coming out of hole w/overshot & picked up new mill & milled on fish for 6 hrs. - Shut down for night
- 12-14-75 Prep to pull mill & started in hole w/overshot & jars - Shut down for night.
- 12-15-75 Shut down for Sunday.
- 12-16-75 Re-ran overshot & jars - Rig broke down - Down three hours for repair - Lack 18 stands being on bottom - Shut down for night.
- 12-17-75 Finished running 2-7/8" tbg. & over shot - Latched on fish & jarred 2-1/2 hrs. w/no success - Ran string shot across pkr. slip area - Fish did not come loose - Jarred on fish for 1 hr. w/no success - Pulled up 18 stands & shut down for night.