

NO. OF COPIES RECEIVED

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 23 1977

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

DISTRIBUTION

SANTA FE

FILE

U.S.G.S.

LAND OFFICE

OPERATOR

O. C. C.
ARTEZIA, OFFICE

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)1. OIL ☐ GAS ☐ OTHER- DRY HOLE
WELL WELL

7. Unit Agreement Name

WILDCAT-DELAWARE

8. Farm or Lease Name

TOM LEE

9. Well No.

#1

10. Field and Pool, or Wildcat

2. Name of Operator

PADER WELL SERVICING CO.

3. Address of Operator

BOX 1772, HOBBS, NEW MEXICO 88240

4. Location of Well

UNIT LETTER C 1230 FEET FROM THE N LINE AND 1980 FEET FROM

THE W LINE, SECTION 29 TOWNSHIP 22-S RANGE 27-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3552 RT

12. County

EDDY

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐PLUG AND ABANDON ☐CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOBS ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in - rigged up.
- Ran tubing to 3250'
- Set 100' plug - 40 sx. cement to 3100'
- Pulled on 9-5/8" and cut off at free point
- Pulled 9-5/8" and set plug @ 1550' (60 sx.)
- Set 100' plug @ 310'-410' (100 sx.)
- Set 10 Sx. plug @ surface.
- Weld 13-3/8" plate inside surface pipe
- Rig down. Clean location. Move off.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE PRESIDENT

DATE 2/18/77

APPROVED BY

TITLE

DATE

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

JUL 31 1975

Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-entry - Delaware Test		7. Unit Agreement Name	
2. Name of Operator Saber Well Servicing Co. ✓		8. Farm or Lease Name Tom Lee	
3. Address of Operator P. O. Box 1772, Hobbs, New Mexico 88240		9. Well No. I	
4. Location of Well UNIT LETTER C , 1230 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 22-S RANGE 27-E N.M.P.M.		10. Field and Pool, or Wildcat Wye-Delaware	
15. Elevation (Show whether DF, RT, GR, etc.) 3552 RT		12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> Recomplete	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Install BOP
2. Pick up tubing and displace hole w/KCL Water to 4000 Ft.
3. Come out of hole and perforate well from 3260 - 3290 - 2 shots per ft.
4. Run 9 5/8" packer on tubing and set at 3229'.
5. Swab dry and acidized w/mud acid -- 500 gal. Formation broke at 1800 lbs.
6. Swab well--making water and slight show of gas.
7. Install pumping unit and pumping well from 3350'.
8. Recovering KCL water and slight show of gas.
9. Unable to determine test of well at this time.

12. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Guy L. Loh* TITLE President DATE 7/29/75

APPROVED BY *W. A. Gressett* TITLE Assistant Secretary DATE 7/29/75

CONDITIONS OF APPROVAL, IF ANY: