Page 3 Form C-103	
3-31-76	S.I. to connect test unit @ 11:20 AM. on 3/4" chk. SITP 300# Opened to unit @ 11:30 AM. 19 hrs. prod. 1000 Mcf/d rate. 19 BC & 79 BSW. FTP 200#. Load to recover 360 BW.
4-1-76	RDMO Unit. Released @ 10:00 AM. Flwd. 30 BC & 71 BSW on 3/4" chk. Gas Volume 1.5 MMcf/d
4-2,3,4,5,-76	FTP 250#. Flwd. 174 BC & 95 BW on 3/4" chk. Gas volume 1.3 MMcf/d S.I. 12:00 Noon 4-5-76 SITP 1850#.
4-6-76	R.U. Otis Wireline Unit & attempted to retrieve XX plug @ 11,083' Unableto retrieve. Made 5 runs w/bailer. Rec'd rubber & scale. Last run w/bailer indicated on top of plug. SDFN
4-7-76	SITP 1950# (Strawn) Made 6 runs w/bailer to 11,083'. Rec'd small amt. scale & sand. No recovery last run. TIH w/pulling tool & equalizing prong. Latched "XX" plug & pulled same. TIH w/Otis type "S" crossover & set @ 10175-10183'. Sheared off tool. TOH RD Otis @ 7:30 PM. Strawn will now be produced thru tbg. & Morrow thru csg.
4-8-76	SICP 1875#. SITP 2000#. Opened tbg. @ 4:00 PM. on 16/64" chk. 14 hrs. Strawn produced 11 BC & O-BW. Gas volume 1000 Mcf/d. FTP 1650#. SI to produce csg.
4-9-76	SITP 2000#. SICP 1875#. Opened csg. on 14/64" chk. 20 hrs. f1wd. 0-BC & 0-BSW. Gas volume 1.6 MMcf/d. FTP 1400# SI.
4-10-76	SITP 2000# SICP 1875#

4-11-76 SITP 2000# SICP 1875# No indication of packer leakage or communication between zones thru-out testing. Official packer leakage test will be performed when new gas contract is negotiated. (As authorized by Mr. W.A. Gressett by phone.) <u>FINAL REPORT</u>