

DAVID FASKEN - WALKER DRAW UNIT # 1

DST # 1, 9490-9615'

Packer failed when reopened. Recovered 730' gas cut mud.

DST # 2, 9610-9650'

Tool open 20 mins. with very weak blow, shut in one hour, reopened with good blow decreasing to very weak blow, left open 1 hour, shut in one hour, recovered 120' drilling mud. IHP 4700, Preflow 64 - 64, ISIP 429, IFP 107, FFP 107, FSIP 579, FHP 4655.

DST # 3, 9750-9830'

Tool open 20 mins., shut in 2 hrs., reopened 2 hrs. with a weak blow increasing to strong blow then decreasing to weak blow, shut in 2 hrs. Recovered 60' drilling mud. IHP 4907, Preflow 64-64, ISIP 1723, IFP 107, FFP 107, FSIP 815, FHP 4844.