

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088

Santa Fe, New Mexico 87504-2088

RECEIVED

MAY - 5 1992

WELL API NO. 0301520728
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. K-3077
7. Lease Name or Unit Agreement Name TERRA STATE
8. Well No. 1
9. Pool name or Wildcat SOUTH CARLSBAD (MORROW)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) DF 3292

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PUMP BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
HAWTHORNE OIL & GAS CORP. ✓

3. Address of Operator
1717 ST. JAMES PLACE, STE. 200 HOUSTON, TX 77056

4. Well Location
Unit Letter **O** : **660'** Feet From The **South** Line and **1980'** Feet From The **EAST** Line

Section **14** Township **23-S** Range **26-E** NMPM **EDDY** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
DF 3292

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 3-25-92 SET BLANKING plug in PKR 11,351. SET 25 SX CNT plug 11,310-11,200. TAG 10,850'
SET 25 SX CNT plug 10,277 to 10,177

2. 3-26-92 TUBING stuck 5459'. CUT to 699400'. SET 70 SX CNT plug 9378'-9029'

3. 3-27-92 SET 30 SX CNT plug 8775'-8630'

4. 4-2-92 SET 25 SX CNT plug 7451'-7350'. SET 80 SX CNT plug 6150'-6050. TAG 5986'

5. 4-3-92 SET 50 SX CNT plug 5296' 5196'. SET 70 SX CNT plug 2036-1880. TAG 1934. SET 40 SX CNT plug to 1880.

6. 4-7-92 SET 80 SX CNT plug. TAG plug 1450'.

7. 4-8-92 SET 80 SX CNT plug to 1360. TAG 1289'.

8. 4-9-92 SET 80 SX CNT plug 415-315. GRABBLE TO TAG plug.

9. 4-10-92 Pumped 12 yds CNT & GRAVEL 415 to 32'. pumped 10 SX CNT 13' to 3'.

10. 4-10-92 CUT OFF WELLHEAD. INSTALL DRY HOLE MARKER

Post ID-2
5-15-92
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry Murray TITLE Agent DATE 4-15-92

TYPE OR PRINT NAME LARRY MURRAY TELEPHONE NO. 915-684-0074

(This space for State Use)

APPROVED BY Mrs. Stillfield TITLE OIL AND GAS INSPECTOR DATE JUN 10 1992

CONDITIONS OF APPROVAL, IF ANY: