

J.M. HUBER CORPORATION
ONEILL FEDERAL PLUGGING REPORT (cont.)

7/12/86 SD, WO location to dry
to
7/14/86

7/15/86 Remove surface equipment. Pits have been filled and location levelled and cleared of junk.

The following casing, tubing, and downhole equip. were left in hole.

13-3/8" csg, 48# & 61#, H-40 & K-55, set @ 600'. None pulled from well
9-5/8" csg, 36#, S-80 & K-55, set @ 5382'. Pulled 1200'
9-5/8", 36#, K-55 csg from well, 4182' of csg left in well.
5-1/2" csg, 15.5# & 17#, S-95 & K-55, set @ 11,883'. Pulled 8032', 5 1/2", 17# & 15.5#, K-55 csg from well, 3851' of csg left in well.

Downhole Equip.: Otis XLB prod. pkr @ 11,650' w/type SN plug set in type "N" profile
Otis Permalatch pkr @ 11,472' w/6"x2-7/8" sub below, 2-3/8"x2-7/8" sub above pkr, 2-3/8"x 5-1/2" overshot tbg seal divider, 2-3/8"x 1-1/2" x-over, 1 jt 1 1/2", 2.76#/ft, J-55 10 rd tbg, 1 1/2"x3' Otis sliding sleeve in open position, 2 jts 1 1/2", 2.76#/ft, J-55 10 rd tbg.