m 9-331 ay 1963)		UN ED STATES MEIL OF THE IN	SUBMIT IN (Other instr		Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND SERIAL NO.
		GEOLOGICAL SURV		AGE 1"	NM 0475051
					6. IF INDIAN, ALLOTTEE OR TRIBE NAME
		fices and repoi			지방수업 등 이 2017 지원들과 2017 운영법
(Do not u	ise this form for propo Use "APPLIC	osals to drill or to deepen o ATION FOR PERMIT—" for	r plug back to a different r r such proposals.)	eservoir.	「「「「「「」」」」である。
	·		RECI	FIVE	7. UNIT AGREEMENT NAME
	WELL X OTHER		REL	. .	· · · · · 국민사님 · · · · · · · · · · · · · · · · · · ·
NAME OF OPER	BATOR			0.0.1074	8. TABM OR LEASE NAME
		Pennzoil Compar	IY APR	2 9 1974	Allied -B-
ADDRESS OF O	PERATOR				9. WELL NO.
	P. 0. Dr	<u>awer 1828 - Midla</u>	and, Texas 7976	<u>C.C.</u>	<u>1</u>
See also space		clearly and in accordance w	ith any State requirements,	N. DEEN	10. FIELD AND POOL, OR WILDCAT
At surface					White City Penn (Morr 11. SEC., T., B., M., OB BLK. AND
175	O' FSL & 1980	' FWL	1		SURVEY OR ABEA
					Sec. 22, T-24-S, R-26-E
PERMIT NO.		15. ELEVATIONS (Show wh	ether DF, RT, GR. etc.)		12. COUNTY OF PARISH 13. STATE
		3319.5			Eddy N.M.
	Check A	ppropriate Box To Indi	cate Nature of Notice,	, Report, or C	ther Data CHARLES TO A State
	NOTICE OF INTE	NTION TO:		SUBSEQU	ENT REPORT OF:
TEST WATER	SHUT-OFF	PULL OR ALTER CASING	WATER SHU	I-OFF	REPAIRING WELL
FRACTURE TR		MULTIPLE COMPLETE	FRACTURE T	REATMENT	ALTERING CASING
SHOOT OR AC		ABANDON*	SHOOTING O	R ACIDIZING	ABANDONMENT [®]
REPAIR WELL	L .	CHANGE PLANS	(Other)		
(Other)			Compl	etion or Recompl	of multiple completion on Well etion Report and Log form.)
DESCRIBE PROD	POSED OR COMPLETED OF work. If well is direct	PERATIONS (Clearly state all ionally drilled, give subsurf	pertinent details, and give ace locations and measured	pertinent dates, and true vertica	including estimated date of starting an l depths for all markers and zones pert
7_25_73	Hole loaded	w/9 8# per gal du			
7-25-73	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme	pipe to 9,500', pipe - 0.K. ment plug 8,800 "7,05 "5,32 ary rig - (Rig r	rilling mudPli ement plugs at fo D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 973 Multiplug missing.
	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,050 " 5,320 ary rig - (Rig ru nt plug 0 5,325'	rilling mudPli ement plugs at fo D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 Market w/25' of cement.
7-27-73	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,	rilling mudPli ement plugs at fo D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 973 Multiplug missing.
7-27-73	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,	rilling mudPli ement plugs at fo D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 Market w/25' of cement.
7-27-73	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,050" " 7,050"	rilling mudPli ement plugs at fo D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 Market w/25' of cement.
7-27-73 3. I hereby cert SIGNED	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,050 ary rig - (Rig ru ont plug 0 5,325' n Bridge Plug 0 is true and correct	rilling mudPl ement plugs at fo D' to 11,130' (1 D' to 11,320' (1 held 400 psi pr 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (1 eleased 9:00 PM to 5,425' w/wir 5,350' on wire 1	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 973 w/25' of cement. w/25' of cement. tinued
7-27-73 3. I hereby cert SIGNED	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,050 ary rig - (Rig ru ont plug 0 5,325' n Bridge Plug 0 is true and correct	rilling mudPl ement plugs at fo D' to 11,130' (1 D' to 11,320' (1 held 400 psi pr 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (1 eleased 9:00 PM to 5,425' w/wir 5,350' on wire 1	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21073 Ment plug missing. w/25' of cement. tinued
7-27-73 3. I hereby cert SIGNED (This space :	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,050 " 5,320 ary rig - (Rig ru ont plug 0 5,325' n Bridge Plug 0 is true and correct 	rilling mudPli ement plugs at for D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir 5,350' on wire 1	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 (73%) (14) (14) (14) (14) (14) (14) (14) (14
7-27-73 3. I hereby cert SIGNED (This space :	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,050 " 5,320 ary rig - (Rig ru ont plug 0 5,325' n Bridge Plug 0 is true and correct 	rilling mudPli ement plugs at for D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir 5,350' on wire 1	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 073 ment plug missing w/25' of cement. tinued all the ball bare not plug missing w/25' of cement.
7-27-73 3. I hereby cert SIGNED (This space :	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " 7,050 " 7,050 " 5,320 ary rig - (Rig ru ont plug 0 5,325' n Bridge Plug 0 is true and correct 	rilling mudPli ement plugs at for D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir 5,350' on wire 1	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 (73%) (14) (14) (14) (14) (14) (14) (14) (14
7-27-73 3. I hereby cert SIGNED (This space) CONDITION APR 2	following ma 60 sk ce 100 sk Pulled drill plug w/drill 35 sk ce 35 sk 35 sk Move off rot Checked ceme Set Cast Iro	nner - Spotted co ment plug 10,980 " " 10,050 pipe to 9,500', pipe - 0.K. ment plug 8,800 " " 7,050 " " 5,320 ary rig - (Rig ru nt plug 0 5,325' n Bridge Plug 0 is true and correct 	rilling mudPli ement plugs at for D' to 11,130' (1 D' to 11,320' (1 held 400 psi pro 0' to 8,900' (1 0' to 7,150' (5' to 5,425' (eleased 9:00 PM to 5,425' w/wir 5,350' on wire 1	ugged and ollowing d Morrow) Atoka) essure on Wolfcamp) Bone Sprin B/9 5/8" c 7-25-73) e line, ce ine & cap Cor	abandoned in the epths: plug for 8 hrs, tag g) asing) AUG21 (73%) (14) (14) (14) (14) (14) (14) (14) (14

,