RECOMMENDED PROCEDURE DRAG "C" WELL #1 CRITICAL December 13, 1982 Page 2

15. Anvell to acidize perfs down 2-7/8" tbg at 5-7 BPM as follows:

- a. Pump 5000 SCF N2.
- b. Pump 5000 gals 152 MSR100 w/1000 SCF N2/bbl. Drop one ball sealer every three bbls acid.
- c. Flush with 2% KCl water w/2000 SCL N2/bbl.
- d. Shut well in for 30 minutes.

16. Flow well back to clean up.

- 17. Frac down 2-7/8" OD tbg with 51,000 gals YF3PSD and 128,000 lbs sand. Frac at 20-24 BPM. Expected treating pressure 5000 psi. Pressure annulus to 1000 psi with standby pump truck. Frac as follows:
 - 18,000 gals YF3PSD pad. ٤. 2,000 gals YF3PSD w/1 ppg 20-40 sd. Ъ. 3,000 gals YF3PSD w/2 ppg 20-40 sd. с. 4.000 gals YF3PSD w/3 ppg 20-40 sd. d. 5,000 gals YF3PSD w/4 ppg 20-40 sd. e. 7.000 gals YF3PSD w/5 ppg 20-40 sd. f. 7,000 gals YF3PSD w/4 ppg 10-20 sd. g. 5,000 gals YF3PSD w/5 ppg 10-20 ds. h. Flush to top perf w/1050 gals WF-30. 1.
 - j. Shut in well for two hours.

18. Flow or swab back load and test.

- Note: A. Reference phone call on abandoning Cisco formation with Les Clements, NMOCC on Tuesday, December 7, 1982, 4:00 p.m.
 - B. Desana's AK State No. 1 2 1/4 mi SE, Bone Springs Discovery Well. Perfs 5496'-5515', CAOF 6.99 MMCFD, BHP 2466 psi, H₂S content 860 grains/MCF.

ANR ANR: JEP: 166