

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES REQUIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

O. C. D.
ARTESIA OFFICE

API No. 30-015-20897

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator

Phillips Petroleum Company

3. Address of Operator

4001 Penbrook Street, Odessa, Texas 79762

4. Location of Well

UNIT LETTER K 1980 FEET FROM THE south LINE AND 1980 FEET FROM

THE west LINE, SECTION 19 TOWNSHIP 23-S RANGE 27-E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name
Drag C

9. Well No.
1

10. Field and Pool, or Whdeat
Carlsbad, S. Morrow

15. Elevation (Show whether DF, RT, GR, etc.)

3205' GR, 3226' RKB

12. County
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Recommended procedure to plug and abandon well:

MIRU wireline unit and plugging unit. NU BOP's. Freepoint 8-5/8" 32#/ft casing. Cut and pull. TIH open-ended to spot cement plugs. Load hole with 9.5 ppg brine. Spot the following plugs using 220 sx Class C with 5% salt, slurry weight 14.9 ppg, Slurry yield 1.33 ft³/sx.

30 sx of cmt from 2150'-2000' + 10'

65 sx cmt across casing cut, tag plug. Must be 50' above casing cut point.

90 sx cmt from 450'-340'.

35 sx from 50' to surface.

Weld on steel plate, install dry hole marker, clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Mueller

TITLE Engineering Supervisor, Reserv DATE October 29, 1987

APPROVED BY Mike Williams

TITLE OIL AND GAS INSPECTOR

DATE NOV 03 1987