	N. M. C		
form 9-331 May 1963)	I TED STATES	SUBMIT IN TI ICAT	
DEPAR	TMENT OF THE INTERI	OR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY		NM-0431054
SUNDRY NO	DTICES AND REPORTS (TN WELLS	6. IF INDIAN, ALLOTTEE OR TLIBE NAM
-			
	posals to drill or to deepen or plug l ICATION FOR PERMIT" for such p	VED	
OIL GAS			7. UNIT AGREEMENT NAME
WELL XX WELL OTHER	An and a second seco	1. TT 1077	8. FARM OR LEASE NAME
Michael P. Grace	JA	N 7 1977	
			Grace Federal Cotton B
P. 0. Box 1),18. Carl	Isbad, New Mexico 8822	\mathbf{O} . C. C.	
LOCATION OF WELL (Report locatio	n clearly and in accordance with any	State requirements."	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface			Wildcat
			11. SEC., T., B., M., OE BLE, AND
1980 FS & W lines Section 34, T22S, R31E		SUBVET OR ABBA	
-			Sec. 34, T22S, R31E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF	, RT, 88, etc.)	12. COUNTY OF PARISH 13. STATE
	3455	KB	Eddy New Mexi
.6. Chark	A B T I H - N	later of https://www.analysia.com	nen en
Check /	Appropriate Box To Indicate N		
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF ;
TEST WATER SHUT-OFF	PULL OR ADTER CASING	WATER SHUT-OFF	KEPAIRING WELL
FRACTCRE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON* XX	SHOOTING OR ACIDIZING	ABANDON MENT*
REPAIR WELL	CHANGE PLANS	(Other)	ults of multiple completion on Well
(Other)]	Completion or Reco	empletion Report and Log form.)
 DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.) * 	ectionally drilled, give subsurface loca	tions and measured and true ve	tes, including estimated date of starting a rtical depths for all markers and zones per to pull sucker rods and
7. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dirent to this work.)* Plan to plug and aba tubing out of hole.	andon this well as soo s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's.	to pull sucker rods and 200'plug
17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dirent to this work.)* Plan to plug and aba tubing out of hole.	andon this well as soo s: Cement plug at Base Cement plug at top Cement plug top of	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's.	to pull sucker rods and 200'plug 200'plug
17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dirent to this work.)* Plan to plug and aba tubing out of hole.	andon this well as soo s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe	to pull sucker rods and 200'plug 200'plug 100'plug
17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dirent to this work.)* Plan to plug and aba tubing out of hole.	andon this well as soo s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe	to pull sucker rods and 200'plug 200'plug 100'plug
7. DESCRIBE PROPOSED OB COMPLETED proposed work. If well is dire nent to this work.)* Plan to plug and aba tubing out of hole. Will plug as follows	andon this well as soo s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou 20' plug surface	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe	to pull sucker rods and 200'plug 200'plug 100'plug
 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dirent to this work.)* Plan to plug and aba tubing out of hole. Will plug as follows 18. I hereby certify that the foregoin 	andon this well as soon s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou 20' plug surface	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe ARTESIA OGICAL	to pull sucker rods and 200'plug 200'plug 100'plug 100'plug
 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is direment to this work.)* Plan to plug and aba tubing out of hole. Will plug as follows 18. I hereby certify that the foregoin SIGNED (Chis space for Federal or State) 	andon this well as soon s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou 20' plug surface	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe ARTESIA OGICAL	to pull sucker rods and 200'plug 200'plug 100'plug 100'plug 1975 DATE <u>12/2/75</u>
 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is direment to this work.)* Plan to plug and aba tubing out of hole. Will plug as follows 18. I hereby certify that the foregoin SIGNED (1990) (This space for Federal or State APPROVED The space of the proposed of t	andon this well as soo s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou 20' plug surface ag is true and correct	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe ARTESIA OGICAL	to pull sucker rods and 200'plug 200'plug 100'plug 100'plug
 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dirent to this work.)* Plan to plug and abatubing out of hole. Will plug as follows 18. I hereby certify that the foregoin SIGNED (This space for Federal or State - APPROVERTRY (The space of the space of the	andon this well as soon andon this well as soon s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou 20' plug surface	n as can get a rig of Salt 3967-4167 of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe	to pull sucker rods and 200'plug 200'plug 100'plug 100'plug 1975 DATE <u>12/2/75</u>
 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is direment to this work.)* Plan to plug and aba tubing out of hole. Will plug as follows 18. I hereby certify that the foregoin SIGNED (1990) (This space for Federal or State APPROVED The space of the proposed of t	andon this well as soon andon this well as soon s: Cement plug at Base Cement plug at top Cement plug top of 15 sks plug over pe 100' plug in and ou 20' plug surface	n as can get a rig of Salt 3967-4167 of Salt 870-1070 2 7/8"stub rf's. t of 13 3/8" shoe ARTESIA OGICAL	to pull sucker rods and 200'plug 200'plug 100'plug 100'plug 1975 DATE <u>12/2/75</u>

-